



**MANCHESTER**  
SCHOOL DISTRICT

# **Jewett Street Elementary School**

Educational and Facilities  
Master Plan

**smma**



# Table of Contents

1. Site Plan
2. Facility Evaluation Criteria
3. Site Evaluation Criteria
4. Educational Assessment
5. Assessment Team Scoring Rubric

## Summary

Included in this report are assets that were collected during the long term facility planning process. Each school's report package contains an At-A-Glance summary report, Facility Evaluation Criteria sheets, and site plan(s). Site plans are included to illustrate the context of the building in relationship to the city, neighborhood, and other adjacent amenities and parcels. The At-A-Glance summary sheets include general information about each school building including school data, such as population and grade structure, etc., site and building data, tax assessor's information, community uses, State of NH Code of Administrative Rules, Operational Data, and Cost model information for repairs and renovations. The Facility Evaluation Criteria sheets are the facility assessment team's findings at each Tier 1 school building including building physical assets, sites, and educational facility effectiveness. On April 24, 2023, the assessment team visited all the Tier 1 school buildings.


SCHOOL NAME

**Jewett Street Elementary School**

SITE VISIT


**August 2023**

# At-a-Glance



FA: Building

FA: Site



### Address

130 South Jewett Street, Manchester, NH 03103



### Gross Square Footage (GSF)

34,436 sf



### Grades

Pre-K–5th Grade



### Site Acreage

47



### Hours of Operation

8:25am–2:50pm



### Date of Construction

1955



### 2022–2023 Enrollment

747



### Date of Addition Construction

1963, 1990

SCHOOL NAME

**Jewett Street Elementary School**

SITE VISIT

**August 2023**

# Site Plans



SCHOOL NAME

**Jewett Street Elementary School**

SITE VISIT

**August 2023**





# Facility Evaluation Criteria

Physical Analysis	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
<b>Roof Membrane (Architectural)</b>					
	<p><i>"Original 1956 and 1961 Additions had new EPDM roofs installed in 2006. Although there is some useful life remaining, there is a significant amount of water ponding throughout. It appears that the original membrane roof in the 1990 addition has not been replaced and the stone ballasting has been removed. Minimal water ponding was observed on this section of roof as well. Roof walkway pads were not installed to and around all HVAC rooftop equipment. All roofs are beyond their useful lifespan and typical warranty period, so replacement is recommended."</i></p>				
<b>Existing Photovoltaics</b>					
	<p><i>"N/A"</i></p>				
<b>Space for Solar on Roof</b>					
	<p><i>"Space on roof is available, exact locations and SF size can be evaluated. HVAC units are in the center of the roof, but generally the roof is not cluttered and there would be spaces for a solar array."</i></p>				
<b>Façade</b>					
	<p><i>"Masonry veneer generally seems to be in good shape except for the brick base at the original building. Significant areas of efflorescence and brick deterioration were observed at the base of walls directly adjacent to paved surfaces. Restoration and repointing will be required."</i></p>				
<b>Windows</b>					
	<p><i>"The original aluminum framed single pane windows and door systems are beyond their useful life expectancy and should be replaced. Window shades have fallen off or have been removed in many spaces. Double pane aluminum windows in the 1990 addition are also nearing the end of their useful like and are not as energy efficient as newer window systems. Window screens are in disrepair or have been removed in many locations. Fiberglass sandwich panels at Multi-Purpose Room show signs of UV degradation."</i></p>				

**Physical Analysis**













NONE / MINOR    
 MODERATE    
 MAJOR    
 REPLACE    
 N/A

<b>Boilers (Mechanical)</b>					
<i>"The boilers are not condensing type and are reaching the end of useful life."</i>					
<b>Boilers (Plumbing)</b>					
<i>"Refer to mechanical report for HVAC boilers. Domestic water heaters - the hot water is heated by a 75-gallon gas fired Bradford White water heater. (76,000 Btu/hr, model number MI75S6BN) The water heater was installed in 2014. The piping arrangement (return piping, circ pump, etc) and equipment appears to be from the same time period or older, but appears in good working order."</i>					
<b>Heating Distribution Systems</b>					
<i>"The heating distribution consists of zone pumps reaching the end of useful life. The piping is older, but the insulation seemed to be in acceptable condition.. For terminal heating equipment, the Classrooms and most spaces use fin tube radiation while the main entrance has radiators, and other locations with more heating requirements have unit heaters."</i>					
<b>Building Envelope Thermal Performance</b>					
<i>"The original 1956 and 1961 portions of the building are mostly brick with CMU backup walls with a 1-1/2" air cavity. Insulation is not provided and does not meet current energy code requirements. When the roof was replaced in these areas in 2003, minimal insulation was added. In the 1990 addition, 2" of insulation exists in the wall cavity, along with 4" of insulation at the roof level. This does not meet current energy code requirements. Original single pane windows are in disrepair and beyond their useful life expectancy. Building entrances and all but one building exit do not have vestibules"</i>					
<b>Interior Finishes</b>					
<i>"Interior finishes are generally old and could use some upgrades. VCT flooring was replaced in 2003 throughout the original portions of the building; however, there are areas of significant VCT cracking at building expansion joints and at exterior doors. Ceilings in the 1956 and 1961 classrooms are the original spline ceilings. Interior casework is generally old and sinks are not accessible. Toilet room finishes are worn and dated in many locations. Although corridor ceilings were updated to ACP in 2003, there are several water stained areas. There are still several existing interior wood doors that are in need of replacement. Classroom door hardware was recently upgraded."</i>					
<b>Rooftop HVAC Equipment</b>					
<i>"The five units for classrooms have recently been replaced and are still in like new condition. The two units serving offices/gym are older and may be getting closer to the end of useful life."</i>					

**Physical Analysis**

 NONE / MINOR
 MODERATE
 MAJOR
 REPLACE
 N/A

<b>HVAC Controls</b>					
	<i>"JCI Metasys controls (District standard) is installed. Thermostats appeared in good condition."</i>				
<b>Technology Infrastructure</b>					
	<i>"Bandwidth of fiber optic and copper network cabling is inadequate for School Communications. Telecom Rooms are not adequately secured allowing staff to use them for storage."</i>				
<b>Technology Systems</b>					
	<i>"Telephone and WiFi systems are at the end of useful life. Network switches have been recently replaced. Not all Telecom Rooms are air conditioned, leaving equipment vulnerable to overheating."</i>				
<b>Security Systems</b>					
	<i>"The City is working with a Security Systems Vendor to deploy 500 CCTV cameras throughout the District's Schools. Adequate bandwidth is a concern for transmitting video. Notification and Lock Down systems are not present. Indoor cellular signal booster system is desired."</i>				
<b>Kitchen Equipment and Systems (Electrical)</b>					
	<i>"Kitchen electrical equipment was observed to be aged, but in fair-to-good condition. All observed receptacles are GFCI type in compliance with Code."</i>				
<b>Kitchen Equipment and Systems (Plumbing)</b>					
	<i>"The kitchen is primarily a warming kitchen. It contains a hand sink and a triple pot sink. The sinks are in fair condition. The piping below the triple pot sink is exposed copper. Chrome plating is recommended."</i>				
<b>Natural Gas Distribution System</b>					
	<i>"The natural gas service supplies gas to HVAC boilers, the domestic water heater, and 8 mechanical roof top units. Piping observations were limited to exposed areas. The piping appears to be in good working order. The gas header runs the length of the gymnasium and is secured to the wall at mid height above the floor."</i>				
<b>Current Fuel Source</b>					
	<i>"The building has a natural gas service fit with a meter and regulator assembly. Based on the arrangement, it appears to be an intermediate pressure line. A 6-inch line rises and enters the building. Although there is some rusting on the piping, the service is in good working order."</i>				

<b>Physical Analysis</b>	 NONE / MINOR	 MODERATE	 MAJOR	 REPLACE	 N/A
<b>Generator</b>					
	<i>"N/A"</i>				
<b>Elevator</b>					
	<i>"N/A"</i>				
<b>Ventilation Distribution Systems</b>					
	<i>"Minimal visible ductwork. Exterior ductwork on new units well insulated and in new condition. Wall grilles appear dirty, but functioning. Principal noted that since new units were installed there have been minimal HVAC complaints from occupants."</i>				
<b>Electrical Services</b>					
	<i>"Electrical service is provided by PSNH via a pad-mounted transformer. The transformer appears to be in good condition. The transformer's secondary feeder is extended underground towards the school building and terminates in the Main Switchboard "MDP" located in the Main Electric room 140. The switchboard is rated 600 Amp 120/208v 3ph 4w, designed/installed during the school renovation project around the year 2003. Power from the MDP is distributed throughout the building via the downstream panelboards. The majority of the downstream panels were replaced during the same 2003 renovation project. Panels were observed in good operational condition. Their power feeders were replaced at the same time. Overall, power equipment throughout the building was observed in good operational condition."</i>				
<b>Life Safety: Means of Egress (Architectural)</b>					
	<i>"Quantity, size and locations of egress components appear to be adequate."</i>				
<b>Life Safety: Means of Egress (Electrical)</b>					
	<i>"Self-contained internally lighted LED exit signs and battery units with remote lights heads are provided along egress pathways. Emergency lighting throughout is observed in adequate operational condition."</i>				
<b>Life Safety: Fire Protection (sprinklers)</b>					
	<i>"The building does not currently have an automatic sprinkler system. Major renovations should include retrofitting the building with sprinklers."</i>				

**Physical Analysis**

● NONE / MINOR    
 ● MODERATE    
 ● MAJOR    
 ● REPLACE    
 ○ N/A

<b>Life Safety: Fire Alarms</b>			<span style="color: orange;">●</span>		
<p><i>"The Fire Alarm system (FA) consists of the FACP, radio master box, smoke and heat detectors, double action pull stations, speaker/strobes and strobe only unit. The Fire Alarm Control Panel (FACP) manufactured by Notifier is located at the main entrance door/ corridor 100. The Knox box is installed on the exterior outside of the main entrance door. Exterior FA alarm beacon was not observed. The school building doesn't have a fire protection system (sprinklers) and therefore there shall be a "full coverage smoke detection" which is not currently present. Smoke detectors were observed only in corridors. Smoke detection devices shall be added throughout the building, to "compensate" for no fire protection system in the building. FA signaling devices (speaker/strobes and strobes) were observed in majority of spaces, however, they appeared missing in some bathrooms and administration area spaces. Additional FA signaling devices shall be provided accordingly. All additional FA initiating and signaling devices shall be connected to FACP."</i></p>					
<b>Security: Entry Sequence</b>			<span style="color: orange;">●</span>		
<p><i>"Administrative offices have direct visual access to the building's front entrance. Card access and a video intercom are installed at the exterior of the main entrance; however, there is not a secured interior vestibule beyond the exterior door."</i></p>					
<b>Lighting Quantity / Control</b>		<span style="color: yellow;">●</span>			
<p><i>"Lighting fixtures in "original" 1955 building areas were observed in "dated" condition, except for some corridors, where the new 2'x4' recessed LED "basket reflector" type lights with integral occupancy sensors were just recently installed. The classrooms and administration area spaces in this building area have non-dimmable surface-mounted linear fluorescent wraparounds, library and bathrooms have 2'x4' lensed troffers. Many lights appear in need for repairs, re-lamping and/or replacements. The multi-purpose room has 2'x2' surface-mounted fluorescent lighting fixtures appearing ?dated?. Occupancy and daylight sensors were not observed in this part of the building. Although still in fair operational condition, the "older" lights are recommended for replacement with energy-efficient dimming types and with associated occupancy sensors and dimming controls. Lighting in 1990 building areas was recently upgraded with 2'x4' recessed LED "basket reflector" type lights with integral occupancy sensors. Lights in 1990 building area are in good operational condition."</i></p>					
<b>Toilets and Fixtures</b>			<span style="color: orange;">●</span>		
<p><i>"The plumbing fixtures appear to be original with the exception of the water fountains (bottle filler type installed). Bubbler outlets at the classroom sinks have been removed and are no longer in use. Flow rates were not able to be confirmed, but based on the age of the fixtures, it is assumed that they are not low flow fixtures. (Would not meet current sustainability requirements.) The toilet rooms within the classrooms do not meet ADA requirements. The mop sink, adjacent to the kitchen, drains very slowly. The piping should be inspected to see if there is a blockage."</i></p>					

**Physical Analysis**

● NONE / MINOR    
 ● MODERATE    
 ● MAJOR    
 ● REPLACE    
 ○ N/A

Plumbing Distribution Systems	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
		●			
<p><i>"Distribution observations were limited to exposed piping within mechanical rooms, exposed within toilet rooms, and under kitchen equipment. The piping near the water heaters looks is a mix of older copper piping and new copper piping. The mixing valve is set at 110 degrees. The piping appears to be in good working order. The water service (2-inch meter and reduced pressure backflow preventer) is located in a corridor closet just inside the main entrance. The age of the copper piping throughout the building varies. Original piping (1955) and piping from the 1963 renovations both exceed the pipes life expectancy (40-50 years). Piping greater than 40 years old should be evaluated (sample destructive testing, water quality testing) to determine the condition and help estimate the longevity left in the piping. Original valves and pipe solder pre-date current lead free regulations and requirements. Exposed sanitary and storm piping where visible appear ok. The condition of the interior of the piping is not known. The expected lifespan of cast iron piping is 50 years. Therefore, original cast iron piping should be scoped/tested to confirm the expectancy left in the piping."</i></p>					

Accessibility (Architectural)	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
			●		
<p><i>"Not all building exits are accessible as they do not exit directly at grade without ramps or sloped walkways. Not all toilet rooms are accessible. Where accessible toilet stalls are provided in several areas, those spaces still do not provide the wheelchair turning radius or required door clearances. Door widths leading into classroom toilet rooms do not meet minimum clear width requirements. A chair lift was installed at the Stage in 1990, however, it is located in a Storage Room and not directly accessible from the Multi-Purpose Room. Classroom sinks are not accessible."</i></p>					

Accessibility (Plumbing)	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
			●		
<p><i>"Fixtures within classroom toilet rooms are not accessible. Listed as major as the door into the rooms are not wide enough to meet ADA requirements. Replacing with assessable door and fixtures will require major rework."</i></p>					

**Structural Systems:  
Signs of Deterioration Observed?**

	YES	NO			
<b>Roof</b>		X			
<p><i>"Roof framing is steel bar joist on CMU bearing walls in some areas and steel framing in other areas. There is a visible roof leak in room 105. Not sure if this is an active leak or an old one."</i></p>					
<b>Floor</b>		X			
<p><i>"Upper level floors are framed with steel bar joists, support on a steel frame or on CMU bearing walls."</i></p>					

SCHOOL NAME

**Jewett Street Elementary School**

SITE VISIT

**August 2023**

REPORT TYPE

**Facility Evaluation**

**Structural Systems:  
Signs of Deterioration Observed?**

	YES	NO
<b>Walls / Columns</b>		<b>X</b>
<i>"All interior walls are CMU walls, with a few drywall partitions scattered throughout."</i>		
<b>Foundations</b>		<b>X</b>
<i>"The foundation walls are in relatively good condition. No visible signs of distress noted."</i>		
<b>Façade</b>		<b>X</b>
<i>"The exterior masonry appears to be in relatively good condition. Some minor masonry repointing is required."</i>		
<b>Is Lateral System Identifiable?</b>	<b>✓</b>	
<i>"CMU bearing and shear walls."</i>		

**Community**

	YES	NO
<b>Emergency Shelter</b>	<b>✓</b>	
<i>"Staff and Family Shelter only."</i>		
<b>Are there Separate Community / Non-School Spaces on Site?</b>		<b>X</b>
<i>"N/A"</i>		



# Site Evaluation Criteria

Physical Analysis	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
<b>Parking Capacity</b>					
<i>"Limited parking for staff only. Signage at Southside indicates some Jewett St Staff may park at the middle school and walk over, suggesting parking capacity on site is inadequate."</i>					
<b>Parking Quality</b>					
<i>"Site in process of repaving."</i>					
<b>Ground Cover</b>					
<i>"Landscaping in decent condition. Minimal shading."</i>					
<b>Fields</b>					
<i>"Multi-purpose field down slope from school. Stairwell to field presents accessibility challenges. Some evidence of erosion down slope and into field from pavement runoff."</i>					
<b>Neighborhood Streets</b>					
<i>"Sidewalk and crosswalk connections to neighborhood streets off Jewett St."</i>					
<b>Drop-off / Pick-up Routes</b>					
<i>"Signage indicates parking lot and drop off loop for staff and buses only. Parent dropoff along Jewett St only. Traffic and safety concerns with on street drop off. No ADA accessible route from street down to school entrance."</i>					
<b>Walkways / Curbs / Sidewalks</b>					
<i>"Walkways and fire land around building currently in process of repaving. Bituminous sidewalk with granite curb along Jewett St, in varied condition. Does not connect directly to sidewalk or plaza at the building. Pedestrians must take stairs or walk in the bus/vehicle right of way."</i>					

SCHOOL NAME


**Jewett Street Elementary School**


SITE VISIT

**August 2023**

REPORT TYPE

**Site Evaluation**

<b>Physical Analysis</b>	 NONE / MINOR	 MODERATE	 MAJOR	 REPLACE	 N/A
<b>ADA Accessibility</b>					
	<i>"Accessible entrances to building. Curb cuts and crosswalks along Jewett St, but sidewalk in poor condition, and no accessible route from sidewalk at street to building. Stairs or grass slope required to get from building up to playground or down to field."</i>				
<b>Site Lighting (Civil)</b>					
	<i>"light fixtures attached to wooden utility poles."</i>				
<b>Site Lighting (Electrical)</b>					
	<i>"Building-mounted wall packs are outdated, not energy-efficient type, observed to be in fair condition. Upgrading to energy-efficient LED lights is recommended. Pole-mounted lights appear to be owned by the utility company."</i>				
<b>Fencing</b>					
	<i>"Security fence between play area and Jewett St."</i>				
<b>Drainage</b>					
	<i>"Catch basins in staff parking lot and bus drop off loop. Paved area in read of school sheet flows to field (without curbing). Evidence of significant erosion where runoff discharges down slope to field."</i>				
<b>Play Areas</b>					
	<i>"Playground in good condition. Site also contains paved areas for play and multi-purpose field."</i>				
<b>Monuments and Memorials</b>					
	<i>"None observed at this site."</i>				
<b>Walls / Slopes</b>					
	<i>"Grassed slopes from Jewett St and playground down to school, and from school down to field. Not significantly steep, but cause some accessibility challenges."</i>				

<b>Physical Analysis</b>	YES	NO
<b>Are there any Wetlands on Site?</b>		
	<i>"GIS and record drawings indicate wetlands in wooded/meadow area along rear of site and at southern end of building where the drainage system outlets (between Jewett St and church parcel)."</i>	

**Physical Analysis**

	YES	NO
<b>Are there any Easements on Site?</b>	✓	
<i>"May be easement for electrical provider to access utility poles and overhead wires. No easements found in GIS or on record plans."</i>		
<b>Are Play Structures Age-Appropriate?</b>	✓	
<i>"Site contains playground, multi purpose field, and bituminous lot with basketball hoops and pavement markings for play, appropriate for elementary school.. Lots currently in process of repaving, final condition TBD."</i>		
<b>Is there an Outdoor-Learning Area?</b>	✓	
<i>"Covered pavilion with picnic tables, garden area with benches available for outdoor learning and gathering space."</i>		
<b>Should there be a Question on Environmental Justice Populations / Vulnerable Populations?</b>		✗
<i>"Social vulnerability index indicates site is in a "medium" vulnerability area."</i>		
<b>Is the Building Expandable on the Current Site?</b>	✓	
<i>"Possible expansion into paved area around building or into field behind school. Some modulars currently at rear of school. Further expansion may depend on utility easements."</i>		
<b>Is the Site Expandable?</b>	✓	
<i>"Opportunities to expand into the field behind school. Possible to create site connection/expansion between Southside and Jewett schools using vacant land on church parcel. Expansion dependent on wetlands and utility easements."</i>		

**Community Analysis**

	YES	NO
<b>Historical Commission Status: Inventory of Archaeological Assets (Site Review)</b>		✗
<i>"The site is not listed on the National Register of Historic Places (per the National Park Service website) nor the New Hampshire State Register of Historic Places (per the New Hampshire Division of Historical Resources website). The site is also not within the Manchester Historic District or listed as a locally-designated historic site, per Manchester GIS."</i>		

SCHOOL NAME

**Jewett Street Elementary School**

SITE VISIT

**August 2023**

REPORT TYPE

**Site Evaluation**

### Community Analysis

	YES	NO
<b>Are there School Buses?</b>	✓	
<i>"Site includes designated bus drop off loop. School receives 1 MTA bus and 8 SPED buses, per bus counts provided by the district."</i>		
<b>Bikeable?</b>		✗
<i>"No bike lanes along Jewett St, somewhat heavily trafficked road."</i>		
<b>Walkable?</b>	✓	
<i>"Sidewalk and crosswalks along Jewett St connect to surrounding neighborhood streets."</i>		

<b>Traffic Analysis</b>	NONE / MINOR	MODERATE	MAJOR	REPLACE	○ N/A
<b>Parking</b> Parking lot	●				
<i>"2 accessible parking spaces with curb-free access to main entrance but 3 accessible parking signs."</i>					
<b>Parking</b> Parking lot	●				
<i>"SE corner of parking lot missing some pavement resulting in incomplete parking space."</i>					
<b>Sidewalks</b> S Jewett St		●			
<i>"Moderate slope. Steep cross-slope on west sidewalk at 155 S Jewett St driveway."</i>					
<b>Standalone Crosswalks</b> Parking lot	●				
<i>"Only crosswalk across parking lot requires using stairs from S Jewett St. Crosswalk is very long but cars generally do not cross it due to the pavement becoming a play area south of the crosswalk. No crosswalk near parking lot driveway where there is less of a grade and stairs would not be necessary."</i>					
<b>Unsignalized Intersections</b> S Jewett St at Brunelle Ave/Parking lot driveway		●			
<i>"East and west sides have no crosswalk. There are no detectable warning panels on the curb ramps and the crossings should be evaluated for ADA compliancy."</i>					
<b>Unsignalized Intersections</b> S Jewett St at Holly Ave	●				
<i>"No crosswalks. The NE, SE, and NW corners have no detectable warning panels on the curb ramps and the crossings should be evaluated for ADA compliancy."</i>					
<b>Unsignalized Intersections</b> S Jewett St at Vinton St	●				
<i>"Crosswalks on south and west sides. The NE, SE, and NW corners have no detectable warning panels on the curb ramps and the crossings should be evaluated for ADA compliancy."</i>					
<b>Unsignalized Intersections</b> Gerald Connor Cir at accessible parking west driveway	●				
<i>"No crosswalks or detectable warning panels. Pedestrian crossings should be evaluated for ADA compliancy. Unconventional STOP sign on driveway."</i>					



# Educational Facility Effectiveness: Learning Environments (EFE: LE)

## Grade Levels

<b>Building Originally Designed as:</b>	1st Grade–6th Grade
<b>Which Educational Program are you Assessing?</b>	Pre-K–4th Grade
<b>The Grade Configuration this School is Best Suited to:</b>	Pre-K–4th Grade

## Educational Building Analysis

● GOOD     
 ● FAIR     
 ● POOR     
 ● DEFICIENT     
 ● FAILING

	GOOD	FAIR	POOR	DEFICIENT	FAILING
<b>Acoustical</b>		●			
<b>Adjacencies of Learning Environments</b>			●		
<i>"Specials on carts and the school has portable classrooms."</i>					
<b>Environment</b> (Inviting / Stimulating / Comfortable)			●		
<b>Finishes</b>		●			
<b>Furniture</b>			●		
<b>Lighting Quality</b>		●			
<b>Natural Daylighting</b>			●		
<i>"Small or few windows in classrooms."</i>					
<b>Technology: Power</b>		●			
<b>Technology: Wireless</b>		●			
<i>"No fax bc wires too old."</i>					

SCHOOL NAME

**Jewett Street Elementary School**

SITE VISIT

**August 2023**

REPORT TYPE

**EFE: LE Evaluation**

**Educational Building Analysis**

● GOOD    
 ● FAIR    
 ● POOR    
 ● DEFICIENT    
 ● FAILING

<b>Ventilation</b>	<span style="color: green;">●</span>				
--------------------	--------------------------------------	--	--	--	--

**This Site Includes:**

YES                      NO

<b>Accessible</b>		✗			
-------------------	--	---	--	--	--

<b>Play Fields</b>	✓				
--------------------	---	--	--	--	--

*"Yes but bc of homeless population and potential illicit activities happening outside school hours, potential for unsafe items to be found on fields."*

<b>Playgrounds / Areas</b>	✓				
----------------------------	---	--	--	--	--

*"One play structure. PK does not have separate playground."*

**Building Assessment**

YES                      NO

<b>Can the Building Change Typology Easily?</b>		✗			
---	--	---	--	--	--

<b>Can the Building be Transformed Educationally to Serve 21st Century Needs?</b>	✓				
---	---	--	--	--	--

*"With an addition and extensive renovation."*

<b>Can the Building Serve as Swing Space?</b>	✓				
---	---	--	--	--	--

<b>Is the Building between 85%–115% Utilization Rate?</b>	✓				
---	---	--	--	--	--



# Educational Facility Effectiveness: Spaces (EFE)

Space Assessment	QUANTITY	ACTUAL AREA (SF)	MORE INFO
<b>Administration and Guidance</b> (Quantity Varies)	Varies	635	
<b>Art Classroom</b> (Min Area 900 sf or 36 sf / Student)	0	0	
<b>Cafeteria</b> (Min Area 12-15 sf / Student for Max Number of Diners per Lunch Period)	1	3500	LUNCH PERIODS: 3
<i>"Shared with Gymnasium."</i>			
<b>Classroom: General Education</b> (Min Area 900 sf or 36 sf / Student)	12	965	
<b>Faculty Lounge</b>	1	355	
<b>Gymnasium</b> (Min Area 6000 sf)	1	(see Cafeteria)	STAGE: Yes
<i>"Shared with Cafeteria."</i>			
<b>Kindergarten</b> (Min Area 1000 sf or 50 sf / Student)	2	965, 1105	TOILET ROOM: Yes
<b>Media Center</b> (Min Area 1800 sf or 4 sf / Student x Design Capacity)	1	1500	
<b>Music Classroom</b> (Area 1200 sf)	0	0	
<b>Pre-K0/K1</b> (Min Area 1000 sf or 50 sf / Student)	5	850, 860, 930	
<b>Special Education: Resource of Small Group</b> (Area 500 sf)	1	870	
<b>Special Education: Self Contained</b> (Area 950 sf)	1	985	TOILET ROOM: No
<b>Stage</b> (Area 1000 sf)	1	505	

**Space Assessment**

	QUANTITY	ACTUAL AREA (SF)	MORE INFO
<b>Teacher Planning</b>	0	0	
<i>"None observed."</i>			

**Adequacy of Rooms**

	GOOD	FAIR	POOR	DEFICIENT	FAILING
<b>Administration and Guidance</b>		●			
<b>Art Classroom</b>					●
<b>Cafeteria</b>		●			
<b>Classroom: General Education</b>		●			
<b>Faculty Lounge</b>			●		
<b>Gymnasium</b>			●		
<i>"Floors are VCT and slippery for some sports. Gym is undersized and shared with Cafeteria."</i>					
<b>Kindergarten (K2)</b>			●		
<i>"Undersized Kindergarten classrooms."</i>					
<b>Media Center</b>			●		
<i>"Short partitions to create resource areas. Have to go through library to access some classrooms."</i>					
<b>Medical</b>			●		
<b>Music Classroom</b>					●
<i>"On a cart."</i>					
<b>Pre-K0/K1</b>			●		
<i>"ECE and sub-separate Pre-K - Undersized."</i>					
<b>Special Education: Resource of Small Group</b>			●		
<b>Special Education: Self Contained</b>			●		
<b>Stage</b>			●		
<i>"Not wheelchair accessible from audience."</i>					

SCHOOL NAME

Jewett Street Elementary School

SITE VISIT

August 2023

REPORT TYPE

EFE: Space Evaluation

### Adequacy of Rooms

● GOOD     
 ● FAIR     
 ● POOR     
 ● DEFICIENT     
 ● FAILING

<b>Teacher Planning</b>					<span style="color: red;">●</span>
<i>"None observed."</i>					

### Special Education Assessment

YES      NO

<b>18+</b>		✗		
<b>Autism Spectrum</b>		✗		
<b>Cognitively Impaired</b>		✗		
<b>Deaf and Hard of Hearing</b>		✗		
<b>Emotional Disturbance</b>		✗		
<b>English Learners</b>	✓			
<i>"Pull-Out and Push-In"</i>				
<b>Intellectual Disability</b>		✗		
<b>Life Skills</b>		✗		
<b>Medically Fragile</b>	✓			
<i>"PK, Self-Contained"</i>				
<b>PT/OT/Speech</b>	✓			
<b>Reset Program</b>		✗		
<b>Social Emotional</b>		✗		
<b>Title 1</b>	✓			

# Assessment Team Scoring Rubric

## Educational and Facilities Assessment Approach

### Assessment Criteria

Educational and Facilities Assessment (E+FA) Approach - Led by architects, engineers, and educational planners from SMMA and its consultants, and in partnership with each school principal, the team conducted both a facility assessment (to take inventory of the building layout and condition) and an educational assessment (to determine the adequacy of spaces for the educational programs offered) in each building. The following report outlines the team organization, methodology and approach taken to assess the Manchester Public School portfolio over the Spring and Summer of 2023.

### Overall Assessment

Categories and criteria were strategically selected for assessment based on stated objectives, past experience, and nature of the Manchester School District portfolio of buildings. Ultimately, the E+FA team created a customized “Manchester School District methodology” which encompassed approximately 75 areas of criteria, organized either facility or site categories that examined physical components, as well as community components.

# Facility Assessment Criteria

## Facility Assessment: Building Evaluation

Facilities varying in terms of age, design, construction methods, and materials were reviewed to determine the condition of the district's portfolio. Building assessments were performed to determine existing components and/or systems' conditions at a specific point in time. The resulting information was then used to guide recommendations regarding maintenance, renovation, and/or replacement. The assessment team conducted visual inspections to observe signs of deterioration. No exploratory demolition, removing finishes, or viewing above ceilings was conducted. Areas that were hard to reach, off limits, or obscured by other systems that prohibited view of the some building components were not assessed. Systems and categories that were assessed included:

- » Building Envelope
  - › Roof Membrane
  - › Facade
  - › Windows
  - › Thermal Performance
- » Boilers
- » Heating Distribution
- » Interior Finishes
- » Rooftop HVAC Equipment
- » HVAC Controls
- » Kitchen Equipment and Systems
- » Natural Gas Distribution
- » Generator
- » Elevator
- » Ventilation Distribution Systems
- » Electrical Service
- » Life Safety:
  - › Means of Egress
  - › Fire Alarm
  - › Fire Protection: Sprinklers
- » Security: Entry Sequence
- » Lighting Quantity/ Control
- » Toilets and Fixtures
- » Plumbing Distribution Systems
- » ADA/Accessibility
- » Structural Systems (consisting of the following components):
  - › Roof framing: This is the horizontal framing consisting of decking, slabs, joists, beams, trusses, etc.
  - › Floor framing: This is the horizontal framing consisting of decking, slabs, joists, beams, trusses, etc.
  - › Walls and columns: These are the vertical elements that hold up the floors and roof structures.
  - › Foundations: Foundations occur at the base of the building and transfer the weight of the building onto the underlying soils.
  - › Facades: These are the outside walls of the building including many non-structural elements (doors, windows, insulation, vapor barriers, etc.) that are part of the weather enclosure for the building.
- » Lateral System: The lateral system in a building is the structural system that keeps the building from falling over when it is subjected to horizontal loads such as wind and earthquake forces.

## Building Evaluation: Criteria Rating Hierarchy

The facility assessment building evaluations used a quintile classification hierarchy as defined below:

- None / Minor: System or element functioning reliably; routine maintenance and repair is needed.
- Moderate: System or element functioning minimally. Repair or replacement of some components is needed.
- Major: System or element is barely functioning. Repair or replacement of most components is needed.
- Replace: System or element is non-functioning, not functioning as designed, or is unreliable. Total replacement all components is needed.
- Not Present: System or element is non-existent, non-functioning, not functioning as designed, or is unreliable. Replacement is needed.

## Building Evaluation: Physical Analysis Definitions

### **Roof**

Roof Membrane: Apparent condition status noted for the roofing material and flashings. Note any obvious deterioration.

### **Existing Photovoltaics**

Yes / No: Criteria noted. However, presence or absence of photovoltaic did not impact overall building condition.

### **Space for Solar**

Yes / No: Comments, if applicable. Evaluation of whether roof space exists for solar (if there are relatively flat areas for possible future solar panels). Note that the roof structure was not evaluated for structural capacity of future PV panels. Criteria noted; however, presence or absence of photovoltaic panels did not impact overall building condition.

### **Façade**

Description of apparent condition and materials of the exterior walls. Observations of any spalling or disintegration of brick or concrete masonry unit (CMU) walls and the condition of the mortar. Notes if there is any obvious movement or structural cracking, and if there is failure, the percentage of failure. With prefabricated panel system facades, notes the types and apparent conditions of attachment systems, panel material, and whether there is deterioration of the surface or caulking or movement in the panels.

### **Windows**

Description of types and apparent conditions of exterior windows. Considers whether most windows appear to be in good working condition, if windows are transparent or translucent, and if they are single or double-paned.

### **Boilers (Mechanical)**

Review of fuel sources and apparent conditions of boilers.

### **Boilers (Plumbing)**

Observation of heating media (e.g. water or steam) of boilers.

### **Heating Distribution Systems**

Evaluation of type and apparent conditions of piping, type, and apparent corrosion.

***Building Envelope Thermal Performance***

Review of the existing drawings of envelope elements (exterior walls, roof, foundations and slabs). Notes presence of vestibules at building entrances for temperature control.

***Interior Finishes***

Evaluation of types and conditions of interior wall, flooring, and ceiling finishes.

***Rooftop HVAC Equipment***

Review of type and apparent condition of roof top units (RTUs), exhaust fans, and air conditioning equipment, if present.

***HVAC Controls***

Review of types of thermostats and type and apparent condition of Building Management System (BMS) if present.

***Kitchen Equipment and Systems (Architectural)***

Evaluation of adequacy and apparent condition of kitchen equipment.

***Kitchen Equipment and Systems (Electrical)***

Observation of electrical kitchen appliances.

***Kitchen Equipment and Systems (Plumbing)***

Observation of gas kitchen appliances. Observation of apparent condition of kitchen plumbing fixtures, and whether there are separate sinks for handwashing and dishwashing, per health and plumbing codes. Notes if proper fire suppression system exists where required.

***Natural Gas Distribution System***

Review of apparent condition of the natural gas system, how it enters the building and is distributed, and of shut-off valves.

***Generator***

Review of type of generator, type of fuel source, and apparent condition if one is present.

***Elevator***

Evaluation of apparent condition of elevator if present.

***Ventilation Distribution Systems***

Review of locations and apparent condition of fans, ductwork, duct grilles, and other ventilation components.

***Electrical Services***

Apparent condition status noted. Review of available capacity, location and appearance of electrical service and meter age.

### ***Life Safety***

- » Means of Egress:
  - › (Architectural): Evaluation of apparent existence of proper smoke and/or fire doors, and if mechanical hold-open devices appear in good working condition. Notes if egress paths are direct and unencumbered, and whether there are enough exits relative to the facility population.
  - › (Electrical): Review of illuminated exit signs and whether they are in the proper locations and appear to be in good condition.
- » Fire Protection (Sprinklers): Observation of type and age of system and components. Review of maintenance records and certifications, if available.
- » Fire Alarms: Observation of type, age, and appearance of systems. Review of available testing records.

### ***Security***

Entry Sequence: Observes if schools have only a camera/buzzer system at their main entrance or whether the main building entrance is adjacent or near the main office. (Adjacency/proximity of main office to main entrance allows for direct observation of the entire person, as well as control of their movements)

### ***Lighting Quality/Control***

Observed (not measured) light levels at the working surface, type of light fixtures and whether they provide an even dispersion and control of light for general academic tasks as well as for use of technology. Apparent condition, locations, and lighting uniformity are noted.

### ***Toilets and Fixtures***

Review of locations and apparent conditions of fixtures. Notes the maintenance and cleanliness of fixtures and flow of fixtures.

### ***Plumbing Distribution Systems***

Review of piping type, apparent corrosion, and equipment, including presence or absence of water heater & back-flow preventer.

### ***ADA / Accessibility***

- » (Architecture): Observes whether the facility is compliant with the Americans with Disabilities Act (ADA) of 1990 standards. Evaluates adequacy and conditions of ramps, lifts, and elevators and whether every occupiable space in the facility can be accessed by anyone with a disability. Other considerations include compliancy of building elements such as clearances and door hardware.
- » (Plumbing): Evaluation of whether toilet facilities and plumbing fixtures are ADA-compliant.

### ***Structural Systems***

The assessment team conducted visual inspections to observe signs of deterioration. No exploratory demolition, removing finishes, or viewing above ceilings was conducted. Areas that were hard to reach, off limits, or obscured by other systems that prohibited view of the structure were not assessed. Each of the criteria listed below is considered as it relates to the structural elements of the building.

A “Yes” comment in the assessment indicates that we observed signs of deterioration. A “Not Observed” comment in the assessment indicates that we either did not observe any distress in the structural element or were not able to observe the element due to the aforementioned limitations, and this does preclude an unobserved area from distress.

- » Roof structural framing: As the framing is covered by roofing, observations are usually made from below. Water leaks are a common cause of damage to roof framing and part of the visual assessment is to look for signs of water damage. In wood framed structures, visual signs include mold or rotting wood. In structures with metal deck, visual signs include rusting of the deck and in concrete structures it can be cracks with rust stains or spalled concrete, indicated where a section of concrete has broken off (typically caused by water penetrating concrete through small cracks causing the steel reinforcing to rust and expand putting outward pressure on the concrete and causing it to break off).
- » Floor structural framing: Common signs of deterioration in floors can be cracks in floors finishes (such as terrazzo), cracks in the bottom of concrete slabs or beams, water damage like that in roofs and longitudinal cracks (or checks) in wood framing. Cracks in floor finishes while cosmetically objectionable is not necessarily an indication of a structural failure. There are several causes for cracks in wood framing members (joists or beams) which does not necessarily mean the member is structurally inadequate.
- » Walls/columns: Walls are typically framed with masonry, concrete, or wood or light gage metal studs with varying finishes. Columns typically consist of steel, concrete, or wood posts and can also be masonry piers. Common signs of deterioration in concrete and masonry walls are cracks in the walls. Cracks typically run vertically (bottom to top), although in masonry walls the cracks often follow the mortar joints. Cracks in walls can be caused by many factors: shrinkage in the wall due to changes moisture or temperature, movement of the supporting structure, or stresses in the wall caused by other loads. Concrete columns can have spalled concrete, wood posts can have longitudinal cracks (similar to floor members), and masonry piers can have cracks similar to walls.
- » Foundations: Notes the type of foundation. Some types include shallow spread footings (concrete pads) and deep foundations such as caissons and piles that extend deep into the ground. Foundations generally include concrete components and are located below ground – making the system difficult to observe without performing some excavation. Some common signs of deterioration are cracks in foundation walls and areas where there has been vertical movement, indicating some settlement of the structure over time, which can be common. The causes of the cracks are like those described for walls.
- » Facades: The structural components of the façade are typically the wall structure (see “Walls” above) but can also include the structural framing for overhangs or other horizontal elements that are part of the walls. Like in roof framing, moisture is a common cause for distress in facades. Common signs of distress are spalled concrete, cracks in concrete or masonry walls, and rusting steel members such as angle lintels over window and door openings in masonry walls. Note that some of these signs of deterioration do not necessarily indicate a structural deficiency and may only require maintenance.
- » Identifiable Lateral System: Notes the presence and type of lateral load-resisting system, such as steel braced frames or shear walls consisting of concrete or masonry walls. Often, steel braced frames are imbedded within walls, making them difficult to identify. With masonry walls, it can be difficult to determine if a wall is a shear wall or just a partition wall. It is not possible to determine the structural adequacy of shear walls or braced frames without an in-depth investigation and it should be noted that many masonry walls in older buildings have little or no reinforcing. Common signs of distress in concrete and masonry shear walls are like those described for walls above.

# Community Assessment: Building Evaluation

The Community – Building assessment included several categories including historical value, emergency shelter status, and use of community and school within/without the buildings. Historical value reviewed the historic inventory and register status of the building. Because schools are often the largest structure in a neighborhood, the City has designated certain facilities as emergency shelters. Additionally, several schools are directly connected to community centers or utilize adjacent neighborhood facilities for athletics and enrichment. Whether the community utilized the building after hours or on weekends was also considered.

## ***New Hampshire Division of Historical Resources (DHR) Status***

Yes/No; Comment, if applicable. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

## ***Inventory of Historic Assets***

Yes/No; Comment, if applicable. Notes whether the building is listed on any inventory of historic assets. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

## ***State Register of Historic Places***

Yes/No; Comment, if applicable. Notes whether the building is listed on a state Register of Historic Places. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

## ***Locally Designated Historic District***

Yes/No; Comment, if applicable. Notes whether the building is within a local historic district. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

## ***Emergency Shelter***

Yes/No; Comment, if applicable. Criteria noted and considered as part of the overall community building score. A designation by the city does not certify compliance for all state and federal requirements for the designation.

## ***Community-Use Spaces***

Yes/No; Comment, if applicable. These were determined after speaking with school administration during site visits. Community spaces attached to schools were also considered. Criteria noted and considered as part of the overall community building score.

## ***Building Suitability for School Use***

Yes/No; Comment, if applicable. Considered any major life-safety concerns for suitability. Criteria will inform opportunities and constraints for modifying the existing building.

## ***Overall Community Building Rating***

This is a judgment on the part of the reviewer(s) that considers all aforementioned factors, as well as amenities located in proximity to school sites and access to public transportation.

# Facility Assessment: Site Evaluation

The site assessment team performed evaluations at each school facility in the district’s portfolio. These evaluations considered the quality, condition, and capacity of the various exterior spaces of the facility. These spaces included: landscaped, educational, recreational, vehicular and pedestrian areas. This field effort was complimented by a study and research of the sites from web-based resources. The resulting information was then used to guide recommendations regarding maintenance, renovation, and/or replacement.

The diverse scope of site elements for schools varies in their relative impact to education and school operations. Priorities include elements that have large impacts to education and/or incur substantial impact to improve or repair.

- » ADA Accessibility
- » Walkways/Curbs/Sidewalks
- » Play Areas
- » Drainage
- » Parking Quality
- » Drop-Off/Pick-Up Routes
- » Walls & Slopes
- » Site Lighting
- » Fencing
- » Neighborhood Streets
- » Evaluation Criteria

## Site Evaluation: Criteria Rating Hierarchy

The site evaluations were judged on a scale as defined below:

- None / Minor: Element is functioning reliably and requires a little repair and routine maintenance.
- Moderate: Element is functioning minimally and requires some repair by a specialist.
- Major: Element is barely functioning and requires substantial repair by a specialist.
- Replace: Element is not functioning correctly and requires total replacement.
- Not Present: Element does not exist or completely failed. This element should be replaced and/or provided. In some instances (parking, walls/slopes and fencing) this element is not required.

## Site Evaluation: Physical Analysis Definitions

### ***Parking & Vehicular Circulation***

Quality of vehicular area paving and quantity of parking spaces considered. This element may not be required if “Not Present”.

### ***Ground Cover***

Presence and condition of landscaping, lawn areas, and any other non-hardscape areas. Ground cover evaluated for aesthetic value, shading, and functionality for outdoor gathering

**Fields**

Presence and apparent condition of athletic or play fields on the property.

**Neighborhood Streets**

Connectivity to residential areas surrounding the site. Condition of adjacent/ off-site roadways, sidewalks, and accessible elements considered.

**Drop-Off/Pick-Up Routes**

Segregation of buses, private vehicles, parking, and neighborhood traffic considered. Both on-site and off-site routes considered. This element may not be required if “Not Present”.

**On-Site Walkways/Curbs/Sidewalks**

Quality of all pedestrian spaces considered.

**ADA Accessibility**

Availability, location, and condition of accessible routes considered. The accessible routes connect building entrances, handicap parking, public streets, and site facilities. Accessibility is considered “Not Present” if there is no accessible building entrance.

**Site Lighting**

Condition, location, and quantity of lighting considered.

**Fencing**

Condition of fencing and gates of various types considered. This element may not be required if “Not Present”.

**Drainage**

Surface ponding, water quality structures, and condition of visible infrastructure considered.

**Play Structures**

Evaluation of apparent condition of play structures and if they are appropriate for range of ages of students at a school, if present.

**Walls and slopes**

Condition of retaining walls and stabilized slopes considered. This element may not be required if “Not Present”.

**Wetlands on site**

Yes/no; proximity of wetlands or natural resources to the site, which – if present – may add restrictions or regulatory challenges to site renovations or expansion.

**Play Areas**

Presence, suitability, and physical condition of casual recreation and play for students. Play structures, surfacing, and courts considered. This element may not be required if “Not Present”.

**Outdoor Classrooms**

Evaluation of apparent condition of outdoor classrooms or learning areas if present.

### ***Environmental Justice Populations***

Review of designation of site and adjacent neighborhoods on the Social Vulnerability Index, per state GIS.

### ***Feasibility of Building Expansion on the Current Site***

Evaluation of whether building is capable of appropriately expanding on its current site. Expansion can be horizontal, vertical, or infill, depending on the building's configuration. Feasibility of expansion based on size of property, existing coverage, regulatory restrictions, and physical constraints such as topography and proximity to natural resources.

### ***Feasibility of Site Expansion***

Evaluation of whether site expansion is possible, based on adjacent properties, and physical constraints, such as roads, proximity to protected lands, and easements.

## **Community Assessment: Site Evaluation**

The Community – Site assessment included the broad categories of transportation access and neighborhood elements. Transportation access considered the condition of the adjacent streets, the ability of students and adults to bicycle and walk to the school, and the accessibility of public transportation. Neighborhood elements considered the school's proximity to community, civic, educational, commercial, and athletic facilities.

### ***New Hampshire Division of Historical Resources (DHR) Status Inventory of Archeological Assets (Site Review)***

Comment, if applicable. Criteria will inform opportunities and constraints for modifying the existing building. In some cases, data may not be available.

### ***School Buses***

Review of types and numbers of school buses and bus queuing.

### ***Accessible to Transit***

Building is located within 2 blocks (1000 feet) of at least 2 stops on bus lines of regular frequency (at least every 10 minutes, during rush hour and mid-afternoon). Criteria noted and considered as part of the overall community building score.

### ***Bikeable***

Facility is considered bikeable if within 2 miles of multiple residential neighborhoods, without riding on busy streets that lack dedicated bike areas. Criteria noted and considered as part of the overall community building score.

- » Wide sidewalks and/or low-traffic streets
- » Adjacent to or within a residential neighborhood, without crossing busy & wide (4+ lanes) streets
- » Not located on a steep street
- » Bike racks are present at the school and are safely accessed from site entry points

**Walkable**

Facility is considered walkable if within 1.4 miles of residential neighborhoods, with consistent sidewalks, and walking route does not require students to cross busy or dangerous streets (per district eligibility criteria).

- » Consistent, accessible sidewalks with crosswalks
- » Adjacent to or within a residential neighborhood, without crossing wide (4+ lanes) streets

**Site suitability for school use?**

Yes/No, Comment if applicable. Considers overall site conditions, overall community rating, and size of site.

**Overall Building – Community Condition:**

This is the professional judgment on the part of the reviewer(s), considering all aforementioned factors and with consideration of nearby neighborhood, community, educational, and athletic facilities. Criteria noted and considered as part of the overall community building score.

# Educational Assessment Criteria

## Educational Facility Effectiveness Evaluation

### Educational Facility Effectiveness of Learning Environments (EFE-LE)

The quality of physical environments has direct impacts on educational outcomes. The EFE analysis considers both inherent building characteristics of physical appearance and condition, and introduced equipment (e.g., furniture and technology). These qualitative factors have a large impact on overall student performance, as they influence students' comfort and ability to concentrate on tasks; teacher and student health and wellness; as well as absenteeism and retention.

Building environments also affect the overall educational effectiveness rating. Fixed elements, such as walls and windows, are components that are not easily remedied and may require extensive or invasive renovation. Other elements, such as furniture or finishes, can be more easily updated, replaced, or supplemented.

Fixed Building Elements include:

- » Ventilation
- » Natural Daylighting
- » Lighting Quality
- » Acoustical
- » Environment (Inviting/Stimulating/Comfortable)
- » Power and Technology Infrastructure
- » Access to water for student projects
- » Access to toilet facilities

Repairing these fixed elements may require buildings to be unencumbered of students (i.e., vacant) for the duration of the work, depending on the upgrades required.

- » Adaptable elements
- » Technology: ubiquitous wireless access for teachers and students and classroom technology
- » Furniture: light weight, ergonomic and supportive of collaboration
- » Finishes
- » Adjacencies of Learning Environments
- » Access to outdoor learning (classrooms or other)

These considerations often consist of singular systems and can be repaired or replaced independent of other systems. They may change frequently with the evolving landscape of educational pedagogy and should support a building that can adapt flexibly at relatively low costs. These upgrades can be executed internally, by facilities personnel or with arranged contracts.

## Educational Facility Effectiveness Evaluation: Criteria Rating Hierarchy

The EFE-LE uses the following classification system:

- Excellent: Elements meet needs for 21st century (Next Generation) teaching and learning
- Good: Elements contribute to teaching and learning
- Fair: Elements somewhat interfere with teaching and learning
- Poor: Elements detract from or interfere with teaching and learning
- Deficient: Non-existent or inoperable systems or elements

## Educational Facility Effectiveness Evaluation: Analysis Definitions

### ***Evaluation Criteria***

**Building Originally Designed As:** Over time, a school building may have modified the range of grades served. Knowing their original use quickly provides some insight into space types and building appointments.

### ***Best Grade Configuration for this School Building***

A school building may be best suited for a different range of grades or use depending on the types, quantities, and sizes of spaces, as well as the existing site attributes, including:

- » Heights of casework, markerboards and other elements the students use
- » Configuration and heights of toilet room fixtures

### ***Ventilation***

Fresh air is a critical component for health, wellness, and overall student performance. An even distribution of ventilated air is also important. Different ventilation systems (unit ventilators, central air ventilation, no mechanical ventilation) provide varying levels of outdoor air percentages and filtration. Observe whether mechanical ventilation is provided and what the apparent quality of the ventilation system is. Qualitative measurements are not taken, however visual, olfactory, and thermal observations are made.

### ***Natural Daylighting***

Considered to be a better quality of light than artificial lighting. Evaluates the general quantity/quality of the natural light and note if most spaces have access to daylight.

### ***Artificial Lighting Quality***

Observed (not measured) light level at the working surface. Type of light fixture and whether it provides an even dispersion of light for general academic tasks, and whether the fixture is dimmable, to accommodate use of technology.

**Acoustical**

The proper balance between voice reinforcement and sound absorption impacts “speech intelligibility.” This includes both sound performance within the space, as well as sound coming from outside the space. Observe whether the space appears to have appropriate acoustical properties for teaching and learning.

**Technology (Power):**

There are enough electrical outlets to support a future technology-rich classroom/school and they are properly distributed throughout the space.

**Technology (Wireless):**

There are sufficient access points throughout the school to support a 1:1 technology environment and fiber optic wiring exists within the building. The main distribution room (server room) is air-conditioned, to ensure system reliability.

**Technology (Interactive):**

Classrooms and other teaching spaces have working interactive technology, such as interactive marker boards and document cameras.

**Furniture**

Different educational-delivery models can be reinforced by furniture type and flexibility. Ideal furniture is light and mobile enough to be easily re-arranged in multiple configurations. Furniture is ergonomic, comfortable, in good condition and promotes student collaboration.

**Finishes**

Materials and conditions of the walls, floors and ceilings. Both physical and aesthetic conditions are considered.

**Environment (Inviting/Stimulating/Comfortable)**

Evaluates whether building is aesthetically pleasing and if it is a place where students and teachers feel comfortable and want to spend time in each day.

**Adjacencies of Learning Environments**

Classrooms and other learning environments have a relationship to each other which promotes collaboration, communication, and other aspects of 21st century teaching and learning. Spaces promote interdisciplinary learning.

**Outdoor Classrooms**

Students have access to outdoor classrooms or other outdoor learning opportunities to learn in different ways, sometimes involving nature and hands-on activities.

## **Site Components**

### ***Playgrounds/Play Areas***

Description of play surface materials (hard or soft). Evaluates condition of on-site play structures and whether structures are age-appropriate to the school's student population.

### ***Accessibility***

Evaluates conditions of play areas, including the ground surface/material, and whether areas are accessible to children of various disabilities.

### ***Play Fields***

Describes conditions of play fields, if present, and whether fields natural grass or synthetic turf.

### ***Flexibility in Building Typology***

Evaluates whether the building can serve alternative grade levels or support a special needs-focused curriculum.

### ***Educational Transformation to Support 21st Century Needs***

Evaluates if the building's construction easily allows for renovations that may change room sizes, replace or upgrade mechanical and electrical systems, and accommodate alternative educational-delivery methods (e.g., project-based learning [PBL]). This can often be the largest difference between a modern steel-frame building and interior masonry-bearing wall construction.

### ***Building as Swing Space***

Assuming the building is otherwise unoccupied, the ability to use the building for educational purposes for the temporary relocation of a school population during a period of renovation or construction.

### ***Utilization Rate***

Description of the utilization rate and if it is 85% or higher. For high schools, classroom utilization of 85% are considered at capacity. Rates higher than 85% show levels of overcapacity and overcrowding. Middle schools generally work to a utilization of 90% and elementary schools at near 100%.

# Educational Facility Spaces Effectiveness Evaluation

The Educational Facility Effectiveness – Spaces (EFE-S) metric compares the sizes of educational spaces to the New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines for 21st century teaching and learning in new capital projects. This quantitative analysis is important for establishing the level of adequacy of the existing spaces for educational delivery. It also indicates whether a facility is deficient/missing dedicated educational spaces normally found in buildings of its grade level and typology.

Primary considerations often affect core curriculum and include:

- » Classrooms (Depending on typology, these may include Pre-K and Kindergarten)
- » Teacher Planning
- » Small Group
- » Science
- » Art
- » Music
- » Vocations and Technology
- » Media Center
- » Cafeteria

Secondary considerations may allow for district flexibility in programming and community resources outside the traditional building environment, and include:

- » Gymnasium (This program space is sometimes served by local community spaces)
- » Gymnasium Options
- » Auditorium
- » Stage
- » Medical
- » Administration & Guidance
- » Air Conditioned Technology Network Room
- » Other considerations
- » Special Education: Self-Contained
- » Special Education: Resource or Small Group

Note: If a school has a special education program, its quantity of spaces will vary. Also, some substantially separate programs do not require full-size classrooms to be effective. For this reason, special education was considered differently than typical classroom spaces.

## Educational Facility Spaces Effectiveness Evaluation: Criteria Rating Hierarchy

The educational facility effectiveness assessment for spaces used a quintile classification hierarchy as defined below:

- Excellent: Exceeds New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines (+10% or greater)
- Good: School facilities are appropriate to house current enrollment and educational program. NSF meets New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines (-10% to +10%)
- Fair: School facilities appear to be adequately sized for current enrollment and educational program. NSF somewhat less than New Hampshire Code of Administrative Rules, Section Ed. 321 (-10% to -20%)
- Poor: School facilities may not be adequately sized for current enrollment and educational program. Net square footage (NSF) at least 20% less than New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines
- Deficient: Dedicated space does not exist.

## Educational Facility Spaces Effectiveness Evaluation: Analysis Definitions

### ***Narratives***

The team considered the long-term goals relative to each building's capability of supporting Manchester School District's educational vision for 21st century (next generation) learning and teaching.

### ***Engaged Learning***

Engaging with the curriculum, applying it to an authentic context. Making connections between content areas and values/curiosity and interest. Finding connections to the community and making a difference. Public and tangible products. There is selective and intentional engagement, and agency in how one keeps focused and takes breaks.

- » The following were criteria used for evaluating the levels of Engaged Learning at each school:
- » The building (is/is not) comfortable to learn in.
- » The building (has/lacks) appropriate temperature control and ventilation.
- » The building (has/lacks) a space that can be used as a flexible learning commons for collaborative learning and presentations.
- » The building (makes use/does not make use) of public space for teaching and learning.
- » The building (provides/lacks) display space for student work to reinforce student accomplishments.
- » The building (provides/lacks) space for teacher collaboration and planning.

### ***Differentiated Learning***

Acknowledging different learning styles. Encouraging how to understand one's self (self-knowledge). Flexibility that occurs within instruction, which also promotes flexibility in how students demonstrate learning. The following were criteria used for evaluating the levels of Differentiated Learning at each school:

- » Classrooms (are/are not) large enough to support Universal Design for Learning (UDL), including the ability to create learning zones.
- » The building (has/lacks) breakout spaces for differentiated/personalized learning and special education.
- » The furniture in the building (can be/has difficulty being) flexibly arranged.

### ***Cognitively Demanding Tasks/Programs***

- » The classroom environment (is/is not) sufficiently flexible to allow for different teaching and learning styles.
- » Building (supports/lacks) learning environments that support music.
- » Building (supports/lacks) learning environments that support art.
- » Building (supports/lacks) learning environments that support physical activity/education.
- » The building environment (supports/does not support) STEM adequately.
- » The building (provides/lacks) space to experiment, create and collaborate.
- » The building (has/lacks) performance/presentation space.
- » Based on location and proximity to community resources and public transportation, teachers and students (can/have difficulty) access(ing) the City as a learning tool.

## **Overall EFE Rating**

NH Code of Administrative Rules, Section Ed. 321 areas are based on current enrollment within school. Actual areas were determined by measuring CADD plans provided by Manchester School District. SMMA did not field-measure the buildings but verified general conformity with existing conditions by measuring spot values to determine the rough accuracy of CADD drawings. The design team reviewed the 2018 CMK Long-Range Facilities Plan, which informed some of the educational effectiveness ratings.

The following outlines the rating system used for evaluating the Overall Educational Facility Effectiveness:

- Excellent: Elements meet needs for current AND future teaching and learning.
- Good: Elements contribute to teaching and learning.
- Fair: Elements somewhat interfere with teaching and learning.
- Poor: Elements detract from or interfere with teaching and learning.
- Deficient: Non-existent or inoperable systems or elements.

