



MANCHESTER
SCHOOL DISTRICT

Parkside Middle School

Educational and Facilities
Master Plan

smma



Table of Contents

1. Site Plan
2. Facility Evaluation Criteria
3. Site Evaluation Criteria
4. Educational Assessment
5. Assessment Team Scoring Rubric

Summary

Included in this report are assets that were collected during the long term facility planning process. Each school's report package contains an At-A-Glance summary report, Facility Evaluation Criteria sheets, and site plan(s). Site plans are included to illustrate the context of the building in relationship to the city, neighborhood, and other adjacent amenities and parcels. The At-A-Glance summary sheets include general information about each school building including school data, such as population and grade structure, etc., site and building data, tax assessor's information, community uses, State of NH Code of Administrative Rules, Operational Data, and Cost model information for repairs and renovations. The Facility Evaluation Criteria sheets are the facility assessment team's findings at each Tier 1 school building including building physical assets, sites, and educational facility effectiveness. On April 24, 2023, the assessment team visited all the Tier 1 school buildings.


SCHOOL NAME

Parkside Middle School

SITE VISIT


August 2023

At-a-Glance



FA: Building

FA: Site



EFE: Learning

EFE: Spaces



Excellent

Deficient



Address

75 Parkside Avenue, Manchester, NH 03102



Gross Square Footage (GSF)

118,550 sf



Grades

5th Grade–8th Grade



Site Acreage

23



Hours of Operation

7:25am–2:20pm



Date of Construction

1967



2022–2023 Enrollment

824



Date of Addition Construction

1999

SCHOOL NAME

Parkside Middle School

SITE VISIT

August 2023

Site Plans



SCHOOL NAME

Parkside Middle School

SITE VISIT

August 2023





Facility Evaluation Criteria

Physical Analysis	● NONE / MINOR	● MODERATE	● MAJOR	● REPLACE	○ N/A
Roof Membrane (Architectural)				●	
<i>"All roofs are beyond their useful lifespan and typical warranty period, so replacement is recommended."</i>					
Existing Photovoltaics					○
<i>"N/A"</i>					
Space for Solar on Roof					○
<i>"Space on roof is available, exact locations and SF size can be evaluated."</i>					
Façade		●			
<i>"Masonry appears to be in good shape throughout. Aluminum vertical fins are damaged in several areas at the base. Paint and finishes are chipping at exterior doors, columns and canopies in several areas."</i>					
Windows			●		
<i>"Windows and curtainwall systems in the original building are single paned glazing and are at the end of their useful life expectancy. Windows in the 1999 addition are double paned aluminum window systems. Several exterior doors and windows were replaced in 1999 with insulated aluminum systems."</i>					
Boilers (Mechanical)	●				
<i>"Boilers are relatively new and appear to be in good working condition. Pumps are also new with ECM primary and new secondary pumps."</i>					
Boilers (Plumbing)	●				
<i>"Refer to mechanical report for HVAC boilers. The domestic hot water is fed from a Lochinvar model AWN501PM (500,000 btu/hr) boiler. The system includes two 119 gallon storage tanks. The boiler was manufactured in 2019 while the storage tanks were manufactured in 2018. The system is in good working order. There is also an electric water heater in the custodian closet (next to room 213). It is assumed that these feeds remote fixtures far away from the source. The 1999 addition also includes a gas fired water heater to serve the addition fixtures."</i>					

Physical Analysis

● NONE / MINOR
 ● MODERATE
 ● MAJOR
 ● REPLACE
 ○ N/A

Heating Distribution Systems		●			
<i>"Classrooms and other spaces have fin tube radiation along the exterior. Some fin tube is missing it's enclosure, not sure if that was part of cleaning or that they need to be replaced. Cabinet unit heaters at entrances. Piping and insulation appear to be in good working condition. There was some eclectic fin tube in stairs where it would be hard to pipe, also appeared to be in working condition."</i>					
Building Envelope Thermal Performance		●			
<i>"Original building (1967) only has minimal building insulation at walls, roof and slab. The 1999 classroom addition includes 2" of insulation at the walls and an air vapor barrier. This does not meet current energy codes. Not all building entrances have vestibules."</i>					
Interior Finishes		●			
<i>"Interior finishes have been well maintained. Most of the VCT flooring in the classrooms was replaced in 2004. Also, in 2004 most spaces were painted and new toilet compartments were installed at the ganged toilet rooms. They appear to still be in good shape. Original tile in toilet rooms is worn and dated. 2x4 ceiling tiles are prone to warping and bowing. Gym wood flooring is in good shape"</i>					
Rooftop HVAC Equipment				●	
<i>"Rooftop equipment appears to be well maintained and in working condition, but much of the equipment is reaching the end of useful life. Units are generally heat recovery units without any cooling capacity. Exhaust fans look like they have been replaced more recently."</i>					
HVAC Controls			●		
<i>"Building Controls are JCI Metasys (district standard) with various types of thermostats."</i>					
Technology Infrastructure				●	
<i>"Bandwidth of fiber optic and copper network cabling is inadequate for School Communications. Telecom Rooms are not adequately secured allowing staff to use them for storage."</i>					
Technology Systems				●	
<i>"Telephone and WiFi systems are at the end of useful life. Network switches have been recently replaced. Not all Telecom Rooms are air conditioned, leaving equipment vulnerable to overheating."</i>					

Physical Analysis

● NONE / MINOR
 ● MODERATE
 ● MAJOR
 ● REPLACE
 ○ N/A

	●	●	●	●	○
Security Systems		●			
<i>"The City is working with a Security Systems Vendor to deploy 500 CCTV cameras throughout the District's Schools. Adequate bandwidth is a concern for transmitting video. Notification and Lock Down systems are not present. Indoor cellular signal booster system is desired."</i>					
Kitchen Equipment and Systems (Electrical)		●			
<i>"Kitchen electrical equipment (panels and receptacles) is found to be aged, but still in fair-to-good condition. Panels are manufactured by Federal Pacific (FPE). Non-GFCI receptacles in kitchen areas shall be replaced to comply with Code."</i>					
Kitchen Equipment and Systems (Plumbing)		●			
<i>"The kitchen includes gas fired equipment. The hood is protected by a wet chemical suppression system (with an agent tank mounted in the room). The triple pot sink does not have a point of use grease trap. Pot sinks and equipment appears in fair working order. Piping is a mix of exposed copper, chrome plated, and PVC. There is exterior pipe discoloration on the metal piping below the sinks. The piping is old and could use replacement. The PVC piping is in very good condition. Although PVC is an acceptable material for waste piping in the NH plumbing code, it is not typically installed in commercial kitchens as there are durability and cleanliness concerns."</i>					
Natural Gas Distribution System	●				
<i>"The natural gas enters the building in two locations and feeds the gas fired boilers, domestic hot water boiler and kitchen equipment. Visual inspection of the gas lines was limited to areas with exposed piping. Above ceiling piping was not observed. The exposed portions of the piping system appears in good working order."</i>					
Current Fuel Source	●				
<i>"The building has a natural gas service fit with a meter and regulator assembly. A 1-inch line rises from underground, goes through a 1 1/2-inch regulator, increases to a 2-inch regulator, and goes back down as a 1-inch pipe. The underground main feeds two services into the building. These lines have regulators only, with no meter. The main meter accounts for both services. Piping is rusted in a few locations. Replacement or painting is recommended for any major renovations."</i>					
Generator					○
<i>"N/A"</i>					

Physical Analysis

● NONE / MINOR
 ● MODERATE
 ● MAJOR
 ● REPLACE
 ○ N/A

Elevator		●			
<p><i>"The elevator was installed in 1999 with the new classroom addition. Due to age of elevator, controls replacement may be required and cab finishes need to be updated."</i></p>					
Ventilation Distribution Systems		●			
<p><i>"Boiler room has combustion air intake with motorized damper. Most rooms seem to have ceiling supply and low wall return. Ductwork on roof is generally in good condition although is not insulated and showing substantial rust in some portions. Gym has high supply and low return. Bathrooms have ceiling exhaust. Dishwasher has direct connected exhaust and hood over cooking equipment. Dryers are exhausted directly to the outside."</i></p>					
Electrical Services		●			
<p><i>"Exterior pad-mounted utility transformer by PSNH is located adjacent to the Main Electric room. It appears in good condition. The utility transformer's secondary feeder is terminated in the Main Switchboard rated 3,000 Amp 277/480v 3ph 4w, located in the Main Electric room 115. The switchboard appears aged, "original" to the building constructed around year 1965, which would make it beyond its useful life expectancy (usually about +/- 40 years), and therefore it's recommended for replacement. Additionally, the switchboard is manufactured by Federal Pacific (FPE) which were discontinued since around year 1980, and considered unreliable by experts these days. Panels fed downstream from the main switchboard are installed throughout the building, both surface- and recessed-mounted. They consist of the "older" (appear to be installed around year 1965 construction) and "newer" (added during building addition around year 1991). Overall, the majority of downstream panels are manufactured by Federal Pacific ("older" and "newer", same as the main switchboard), and are recommended for replacement. Power feeders from the Main Switchboard to "older" panels are recommended for replacement."</i></p>					
Life Safety: Means of Egress (Architectural)		●			
<p><i>"Stair guardrails in original portions of the building do not meet code required heights. Egress stairs in original portions of the building do not have continuous handrails on the inner side. Quantity and locations of egress stairs and doors appear to be adequate."</i></p>					

Physical Analysis

 NONE / MINOR
  MODERATE
  MAJOR
  REPLACE
  N/A

<p>Life Safety: Means of Egress (Electrical)</p>					
<p><i>"Self-contained internally lighted LED exit signs are provided along egress pathways in "original" (year 1965) and "addition" (year 1999) building areas. They appear in good operational condition, however, a few corridor areas seemed would need additional exit signs due to the overall corridor length, advised to be re-examined and defined. Emergency egress lights are provided in "original" building by means of battery units with light heads and drop-down ceiling emergency lights. They were observed in adequate operational condition. Emergency lights in "addition" appear in inadequate condition. Emergency lights in corridors and bathrooms were not observed and shall be provided to comply with Code."</i></p>					
<p>Life Safety: Fire Protection (sprinklers)</p>					
<p><i>"The building is currently provided with an automatic sprinkler system. The service includes control check valves and zone control valves. (First floor, second floor) A double check valve was not present. (Current regulations require a backflow preventer at the service to protect the city water supply from cross connection). A fire department connection and electric bell are installed on the exterior wall (outside room 130). The building is fully sprinklered. There are a mix of sprinkler types. The area below the stage is also protected by sprinklers."</i></p>					
<p>Life Safety: Fire Alarms</p>					
<p><i>"Existing Fire Alarm (FA) system appears addressable, consisting of smoke and heat detectors, double action pull stations, speaker/strobes and strobe only unit, and connections to fire protection equipment. The Fire Alarm Control Panel (FACP) is manufactured by Notifier. The exterior remote Fire Alarm Annunciator (FAA) is manufactured by Simplex. FACP and radio master box are in the main entrance vestibule. All classrooms and similar educational spaces, corridors, teacher areas, etc. are equipped with signaling devices. Overall, the FA system equipment was observed in good operational condition."</i></p>					
<p>Security: Entry Sequence</p>					
<p><i>"Main entrance has controlled card access. A transaction window at the main entrance vestibule was added in 2004 providing added security and visual access."</i></p>					

Physical Analysis

● NONE / MINOR
 ● MODERATE
 ● MAJOR
 ● REPLACE
 ○ N/A

Lighting Quantity / Control	●	●	●	●	○
<p>Lighting Quantity / Control</p> <p>"Overall, lighting was observed in good operational condition. Lighting in "original" building areas was recently upgraded. Classrooms, corridors, bathrooms, cafeteria and a few other spaces have 2'x4' and 2'x2' LED recessed "basket reflector" lights with integral occupancy sensors. They appear in good operational condition. The kitchen and a few other spaces have surface-mounted wraparounds, which show some signs of wear. The Gym has suspended LED lights in good operational condition. General offices have 2'x4' "basket reflector" lights with fluorescent lamps, in good condition. Occupancy sensors were not observed. In building "addition" areas lighting was upgraded in corridors only - the 2'x4' LED "basket reflector" design lights with integral occupancy sensors were observed. They appear in good operational condition. Lighting fixtures in classrooms are 2'x4' recessed "basket reflector" type with fluorescent lamps, no occupancy sensors. They appear in good operational condition. Suggested to add occupancy sensors to comply with Energy Code."</p>	●				
<p>Toilets and Fixtures</p> <p>"The fixtures are outdated and could use replacement in many locations. Drinking fountains have been replaced with bottle filling stations in a few locations, but the old style remains in a few locations as well. The flow rates of the fixtures could not be confirmed, but it is assumed that the fixtures do not meet current low flow sustainability requirements. Replacement fixtures should be low flow type. The boys locker room showers are not operational (some removed). They are not used. The single use girls room and boys room (across from room 226 and room 224 respectively) do not have ADA toilets. Science room sinks include glass acid waste piping. Modifications should include polypropylene piping as glass piping is no longer the industry standard."</p>		●			
<p>Plumbing Distribution Systems</p> <p>"Observations of the plumbing distribution was limited to piping within mechanical rooms and other unfinished areas. The domestic water service has a 2-inch water meter. The age of the copper piping throughout the building varies. Original piping is 56 years old, while the addition piping is 24 years old. Piping greater than 40 years old (40-50 years life expectancy) should be evaluated (sample destructive testing, water quality testing) to determine the condition and help estimate the longevity left in the piping. Original valves and pipe solder pre-date current lead free regulations and requirements. The piping near the water heater was replaced when the hot water heater was installed. Roof drains and vents through the roof are in good working order. However, there were discussions regarding roof leaks on the original building roof. Observations of exposed sanitary and storm piping was limited. The condition of the interior of the piping is not known. The expected lifespan of cast iron piping is 50 years. Therefore, original cast iron piping should be scoped/tested to confirm the expectancy left in the piping."</p>		●			

Physical Analysis

● NONE / MINOR
 ● MODERATE
 ● MAJOR
 ● REPLACE
 ○ N/A

Accessibility (Architectural)			●	
<p><i>"Most entrances and exits are not accessible. Handrails do not meet accessibility codes. Toilet rooms in the original building are not accessible. Several interior doors do not meet the required door clearances. Classroom sinks in the original building are not accessible. Toilet and wall mounted accessories and equipment encroach more than 4? into accessible routes and corridor widths."</i></p>				
Accessibility (Plumbing)			●	
<p><i>"Many of the fixtures are not ADA compliant. Lavatories do not have the pre-molded insulation covering the traps."</i></p>				

**Structural Systems:
Signs of Deterioration Observed?**

YES NO

Roof		X		
<p><i>"Concrete roof slab on steel beams over corridor at main bldg. and at the additions."</i></p>				
Floor		X		
<p><i>"Floors in really good shape. Few cracks in floor visible throughout the building, at addition and original bldg."</i></p>				
Walls / Columns		X		
<p><i>"Exterior and demising walls in classrooms are CMU masonry."</i></p>				
Foundations		X		
<p><i>"Foundation in good condition. There is a small settlement crack at the front of the building. Some of the foundation walls have cracking and spalling at the corners. This is not a major issue, but the cracks should be repaired in the near future to prevent further deterioration of the walls."</i></p>				
Façade		X		
<p><i>"Façade in overall good shape some minor defects noted."</i></p>				
Is Lateral System Identifiable?	✓			
<p><i>"Masonry shear walls. No braced frames observed."</i></p>				

SCHOOL NAME

Parkside Middle School

SITE VISIT

August 2023

REPORT TYPE

Facility Evaluation

Community

	YES	NO
Emergency Shelter	✓	
<i>"Main Shelter for West Campus."</i>		
Are there Separate Community / Non-School Spaces on Site?	✓	
<i>The site abuts a park and community garden. The park area may share parking facilities during non-school hours.</i>		



Site Evaluation Criteria

Physical Analysis	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
Parking Capacity					
	<i>"42 parking spaces for staff and visitors in the front lot. 88 staff per school district website. May share additional parking with adjacent elementary school."</i>				
Parking Quality					
	<i>"Small staff lot and bus drop off loop in OK condition."</i>				
Ground Cover					
	<i>"Some landscaping at front of building. Grassed lawn and wooded area around rear of building. Adjacent parkland includes community garden, providing additional vegetation as well as outdoor learning opportunities."</i>				
Fields					
	<i>"Multi-purpose athletic field, as well as other grassed areas at rear of site and in adjacent park, which could be used for gathering and casual recreational use."</i>				
Neighborhood Streets					
	<i>"School located along low traffic residential street. Additional neighborhood connections through the park to the south and east. Connection to the north via the elementary school site."</i>				
Drop-off / Pick-up Routes					
	<i>"Bus drop off only in the staff parking lot loop. Loading and unloading along adjacent one-way street."</i>				
Walkways / Curbs / Sidewalks					
	<i>"Sidewalks in poor condition. Mix of bituminous and concrete walkways. Vertical granite curb along street and at front entrance, bituminous berm or no curb elsewhere."</i>				

Physical Analysis	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
ADA Accessibility			●		
<i>"2 ADA spaces and ramp at front entrance. Most other egresses around the building are not accessible. Poor condition of sidewalks further limits accessibility. No crosswalks along Park Side Ave directly in front of middle school. Nearest crosswalk one block down at elementary school entrance."</i>					
Site Lighting (Civil)	●				
<i>"Building mounted lights and light fixtures on utility poles around the site."</i>					
Site Lighting (Electrical)	●				
<i>"Exterior building-mounted are a mix of "newer" LED wall packs in good condition and "old" canopy lights which show some signs of wear. The "old" lights shall be replaced with LED energy-efficient types."</i>					
Fencing	●				
<i>"Fencing around playground and athletic field. Security fence around electrical equipment."</i>					
Drainage		●			
<i>"Catch basin at low point near front entrance with some evidence of ponding (may be clogged). Remainder of front parking area runs into drainage network in the street. Area drains in grassed areas around the remainder of building. Some evidence of erosion, sediment buildup, and pavement damage from stormwater."</i>					
Play Areas	●				
<i>"Play structure (shared with elementary school). Basketball courts, soccer/street hockey court, and multi-purpose athletic fields. All in good condition."</i>					
Monuments and Memorials	●				
<i>"None observed at this site."</i>					
Walls / Slopes	●				
<i>"Relatively flat site around building. Slight slope up from Park Side Ave. Slope up into the woods/adjacent park (Derby Hill)."</i>					
Physical Analysis	YES	NO			
Are there any Wetlands on Site?		✗			
<i>"No wetlands per GIS data. No evidence of wetlands, unless deeper within wooded area at rear of site."</i>					

Physical Analysis

	YES	NO
Are there any Easements on Site?		X
<i>"No easements per GIS. Possible shared access easements with adjacent elementary school, or easements for electrical poles."</i>		
Are Play Structures Age-Appropriate?	✓	
<i>"Play structure shared between elementary and middle school. Field, basketball courts, and soccer/hockey court more typical of middle school age."</i>		
Is there an Outdoor-Learning Area?	✓	
<i>"Picnic tables at front and side of school. Possibility for additional outdoor learning at adjacent community garden."</i>		
Should there be a Question on Environmental Justice Populations / Vulnerable Populations?	✓	
<i>"NH GIS designates site as "Medium High" Social Vulnerability Index, based on census analysis."</i>		
Is the Building Expandable on the Current Site?	✓	
<i>"Opportunities to expand towards woods at rear of site or into the area between middle and elementary school (where there is currently a modular classroom). May require relocation of utility poles."</i>		
Is the Site Expandable?	✓	
<i>"May be feasible to expand into adjacent park land, or create more efficient layout between elementary and middle school."</i>		

Community Analysis

	YES	NO
Historical Commission Status: Inventory of Archaeological Assets (Site Review)		X
<i>"The site is not listed on the National Register of Historic Places (per the National Park Service website) or the New Hampshire State Register of Historic Places (per the New Hampshire Division of Historical Resources website). The site is also not within the Manchester Historic District or listed as a locally-designated historic site, per Manchester GIS."</i>		

SCHOOL NAME

Parkside Middle School

SITE VISIT

August 2023

REPORT TYPE

Site Evaluation

Community Analysis

	YES	NO
Are there School Buses?	✓	
	<i>"Designated bus drop off loop in staff parking lot. 4 MTA and 14 SPED buses, per bus counts provided by the district."</i>	
Bikeable?		✗
	<i>"Small bike rack at rear of building. No bike lanes along Park Side Ave."</i>	
Walkable?	✓	
	<i>"Sidewalk and trail connections to adjacent neighborhood streets via Park Side Ave and through the park."</i>	

Traffic Analysis	● NONE / MINOR	● MODERATE	● MAJOR	● REPLACE	○ N/A
Parking Parking lot	●				
<i>"Two accessible parking spaces with curb ramp in between leading to entrance. No detectable warning panel. Striping and arrows starting to fade."</i>					
Pedestrian Connections Behind school	●				
<i>"Path in poor condition with obstructions near shed and utilities. Small segments of path missing on north and south sides near corners of school."</i>					
Pedestrian Connections Parking lot		●			
<i>"Path desired around south side of parking lot between school and Park Side Ave, continuing from existing path. Existing paths and curbs in poor to fair condition."</i>					
Roadway Characteristics Blucher St	●				
<i>"Faded double yellow line near Park Side Ave intersection, while rest of roadway has no striping. Segment near Park Side Ave intersection with no homes prone to speeding."</i>					
Sidewalks Blucher St	●				
<i>"Inconsistent sidewalks starting and ending randomly in fair to poor condition. Not a major issue due to most pedestrians using parallel Park Side Ave."</i>					
Sidewalks Park Side Ave	●				
<i>"Sidewalk only on east (school) side. Poor to fair condition."</i>					
Unsignalized Intersections Blucher St at Park Side Ave/Blucher St E Back		●			
<i>"Fast speeds due to lack of STOP signs and skewed intersection geometry."</i>					
Unsignalized Intersections Blucher St at Park Side Ave/Blucher St E Back	●				
<i>"No crosswalk or detectable warning panels across Blucher St East Back. Pedestrian crossing should be evaluated for ADA compliancy."</i>					

SCHOOL NAME

Parkside Middle School

SITE VISIT




August 2023


REPORT TYPE

Site Evaluation

Traffic Analysis

 NONE / MINOR
  MODERATE
  MAJOR
  REPLACE
  N/A

	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
Unsignalized Intersections Park Side Ave at Loading driveway					
<i>"No crosswalks or detectable warning panels. Pedestrian crossings should be evaluated for ADA compliancy. Signs of water pooling at corners of intersection may indicate drainage issues. No STOP sign."</i>					
Unsignalized Intersections Park Side Ave at Parking lot north driveway					
<i>"No crosswalks or detectable warning panels. Pedestrian crossings should be evaluated for ADA compliancy. Only indication that driveway is exit only is a faded arrow pavement marking, no signage. No STOP sign for driveway approach."</i>					
Unsignalized Intersections Park Side Ave at Parking lot south driveway					
<i>"No crosswalks or detectable warning panels. Pedestrian crossings should be evaluated for ADA compliancy. Only indication that driveway is entrance only is a faded arrow pavement marking, no signage."</i>					



Educational Facility Effectiveness: Learning Environments (EFE: LE)

Grade Levels

Building Originally Designed as:	7th Grade–8th Grade <i>“Originally designed as a Junior High School”</i>
Which Educational Program are you Assessing?	5th Grade–8th Grade
The Grade Configuration this School is Best Suited to:	9th Grade–12th Grade <i>“Needs significant renovations to provide cohesive teaming areas and components.”</i>

Educational Building Analysis

	GOOD	FAIR	POOR	DEFICIENT	FAILING
Acoustical	●				
Adjacencies of Learning Environments			●		
Environment (Inviting / Stimulating / Comfortable)				●	
	<i>“Entrance lobby is large but sits directly across a wall and closed doors. Most corridors are long and undeserved by daylight, particularly the corridors on the bottom level. No dedicated area for students to gather informally in their team areas.”</i>				
Finishes			●		
	<i>“VCT flooring, painted CMU walls, glazed CMU walls (observed cracking and damage, particularly near cafeteria)”</i>				

SCHOOL NAME

Parkside Middle School

SITE VISIT

August 2023

REPORT TYPE

EFE: LE Evaluation

Educational Building Analysis

● GOOD
 ● FAIR
 ● POOR
 ● DEFICIENT
 ● FAILING

	GOOD	FAIR	POOR	DEFICIENT	FAILING
Furniture		●			
<i>"Some rooms had newer furniture."</i>					
Lighting Quality	●				
Natural Daylighting		●			
Outdoor Classrooms		●			
Technology: Power		●			
<i>"More outlets needed in classrooms."</i>					
Technology: Wireless	●				
Ventilation			●		

This Site Includes:

YES NO

	YES	NO		
Accessible		✗		
<i>"Play structure and surrounding ground cover (grass and wood chips) are not accessible to wheelchairs."</i>				
Play Fields		✗		
Playgrounds / Areas	✓			
<i>"Play structure is shared with neighboring Gossler Park. Basketball courts."</i>				

SCHOOL NAME

Parkside Middle School

SITE VISIT

August 2023

REPORT TYPE

EFE: LE Evaluation

Building Assessment

YES

NO

Can the Building Change Typology Easily?	✓		
<i>"School was originally designed as a Junior High School."</i>			
Can the Building be Transformed Educationally to Serve 21st Century Needs?		✗	
<i>"Yes, with significant renovations."</i>			
Can the Building Serve as Swing Space?	✓		
Is the Building between 85%–115% Utilization Rate?	✓		
<i>"Building is overcrowded."</i>			



Educational Facility Effectiveness: Spaces (EFE)

Space Assessment	QUANTITY	ACTUAL AREA (SF)	MORE INFO
Administration and Guidance (Quantity Varies)	Varies	2050	
Art Classroom (Min Area 900 sf or 36 sf / Student)	1	1240	
Cafeteria (Min Area 12-15 sf / Student for Max Number of Diners per Lunch Period)	1	3670	LUNCH PERIODS: 4
Classroom: General Education (Min Area 900 sf or 36 sf / Student)	38	820, 900, 950	
FACS	1	1110	
Faculty Lounge	1	470	
Gymnasium (Min Area 6000 sf)	1	7200	STAGE: Yes
Media Center (Min Area 1800 sf or 4 sf / Student x Design Capacity)	1	3244	
Music Classroom (Area 1200 sf)	3	1000, 1040, 1170	
Science Classroom / Lab (Area 1200 sf or 60 sf / Student)	4	1140, 1180, 1210, 1280	
Small Group	0	0	
<i>"None observed."</i>			
Special Education: Resource of Small Group (Area 500 sf)	5	440, 725, 950, 1000, 1240	
Special Education: Self Contained (Area 950 sf)	4	600, 640, 950, 1050	TOILET ROOM: No

SCHOOL NAME

Parkside Middle School

SITE VISIT

August 2023






















REPORT TYPE

EFE: Space Evaluation

Space Assessment

	QUANTITY	ACTUAL AREA (SF)	MORE INFO
Stage (Area 1000 sf)	1	1115	
Teacher Planning	0	0	
<i>"None observed."</i>			
Technology Lab	1	1070	
<i>"Computer Lab"</i>			
Woodshop	1	1370	

Adequacy of Rooms

	 GOOD	 FAIR	 POOR	 DEFICIENT	 FAILING
Administration and Guidance					
Art Classroom					
Cafeteria					
Classroom: General Education					
FACS					
Faculty Lounge					
Gymnasium					
Media Center					
Medical					
Music Classroom					
Science					
Small Group					
<i>"None observed."</i>					
Special Education: Resource of Small Group					
Special Education: Self Contained					
Stage					
Teacher Planning					
<i>"None observed."</i>					

SCHOOL NAME

Parkside Middle School

SITE VISIT

August 2023

REPORT TYPE

EFE: Space Evaluation

Adequacy of Rooms

● GOOD
 ● FAIR
 ● POOR
 ● DEFICIENT
 ● FAILING

Technology Lab		●		
Woodshop		●		

Special Education Assessment

YES NO

18+		✗	
Autism Spectrum	✓		
<i>"Self-Contained and Travelling"</i>			
Cognitively Impaired		✗	
Deaf and Hard of Hearing		✗	
Emotional Disturbance		✗	
English Learners	✓		
<i>"Push-in / Pull-Out"</i>			
Intellectual Disability	✓		
<i>"Self-Contained"</i>			
Life Skills		✗	
Medically Fragile		✗	
PT/OT/Speech	✓		
Reset Program		✗	
Social Emotional		✗	
Title 1		✗	

Assessment Team Scoring Rubric

Educational and Facilities Assessment Approach

Assessment Criteria

Educational and Facilities Assessment (E+FA) Approach - Led by architects, engineers, and educational planners from SMMA and its consultants, and in partnership with each school principal, the team conducted both a facility assessment (to take inventory of the building layout and condition) and an educational assessment (to determine the adequacy of spaces for the educational programs offered) in each building. The following report outlines the team organization, methodology and approach taken to assess the Manchester Public School portfolio over the Spring and Summer of 2023.

Overall Assessment

Categories and criteria were strategically selected for assessment based on stated objectives, past experience, and nature of the Manchester School District portfolio of buildings. Ultimately, the E+FA team created a customized “Manchester School District methodology” which encompassed approximately 75 areas of criteria, organized either facility or site categories that examined physical components, as well as community components.

Facility Assessment Criteria

Facility Assessment: Building Evaluation

Facilities varying in terms of age, design, construction methods, and materials were reviewed to determine the condition of the district's portfolio. Building assessments were performed to determine existing components and/or systems' conditions at a specific point in time. The resulting information was then used to guide recommendations regarding maintenance, renovation, and/or replacement. The assessment team conducted visual inspections to observe signs of deterioration. No exploratory demolition, removing finishes, or viewing above ceilings was conducted. Areas that were hard to reach, off limits, or obscured by other systems that prohibited view of the some building components were not assessed. Systems and categories that were assessed included:

- » Building Envelope
 - › Roof Membrane
 - › Facade
 - › Windows
 - › Thermal Performance
- » Boilers
- » Heating Distribution
- » Interior Finishes
- » Rooftop HVAC Equipment
- » HVAC Controls
- » Kitchen Equipment and Systems
- » Natural Gas Distribution
- » Generator
- » Elevator
- » Ventilation Distribution Systems
- » Electrical Service
- » Life Safety:
 - › Means of Egress
 - › Fire Alarm
 - › Fire Protection: Sprinklers
- » Security: Entry Sequence
- » Lighting Quantity/ Control
- » Toilets and Fixtures
- » Plumbing Distribution Systems
- » ADA/Accessibility
- » Structural Systems (consisting of the following components):
 - › Roof framing: This is the horizontal framing consisting of decking, slabs, joists, beams, trusses, etc.
 - › Floor framing: This is the horizontal framing consisting of decking, slabs, joists, beams, trusses, etc.
 - › Walls and columns: These are the vertical elements that hold up the floors and roof structures.
 - › Foundations: Foundations occur at the base of the building and transfer the weight of the building onto the underlying soils.
 - › Facades: These are the outside walls of the building including many non-structural elements (doors, windows, insulation, vapor barriers, etc.) that are part of the weather enclosure for the building.
- » Lateral System: The lateral system in a building is the structural system that keeps the building from falling over when it is subjected to horizontal loads such as wind and earthquake forces.

Building Evaluation: Criteria Rating Hierarchy

The facility assessment building evaluations used a quintile classification hierarchy as defined below:

- None / Minor: System or element functioning reliably; routine maintenance and repair is needed.
- Moderate: System or element functioning minimally. Repair or replacement of some components is needed.
- Major: System or element is barely functioning. Repair or replacement of most components is needed.
- Replace: System or element is non-functioning, not functioning as designed, or is unreliable. Total replacement all components is needed.
- Not Present: System or element is non-existent, non-functioning, not functioning as designed, or is unreliable. Replacement is needed.

Building Evaluation: Physical Analysis Definitions

Roof

Roof Membrane: Apparent condition status noted for the roofing material and flashings. Note any obvious deterioration.

Existing Photovoltaics

Yes / No: Criteria noted. However, presence or absence of photovoltaic did not impact overall building condition.

Space for Solar

Yes / No: Comments, if applicable. Evaluation of whether roof space exists for solar (if there are relatively flat areas for possible future solar panels). Note that the roof structure was not evaluated for structural capacity of future PV panels. Criteria noted; however, presence or absence of photovoltaic panels did not impact overall building condition.

Façade

Description of apparent condition and materials of the exterior walls. Observations of any spalling or disintegration of brick or concrete masonry unit (CMU) walls and the condition of the mortar. Notes if there is any obvious movement or structural cracking, and if there is failure, the percentage of failure. With prefabricated panel system facades, notes the types and apparent conditions of attachment systems, panel material, and whether there is deterioration of the surface or caulking or movement in the panels.

Windows

Description of types and apparent conditions of exterior windows. Considers whether most windows appear to be in good working condition, if windows are transparent or translucent, and if they are single or double-paned.

Boilers (Mechanical)

Review of fuel sources and apparent conditions of boilers.

Boilers (Plumbing)

Observation of heating media (e.g. water or steam) of boilers.

Heating Distribution Systems

Evaluation of type and apparent conditions of piping, type, and apparent corrosion.

Building Envelope Thermal Performance

Review of the existing drawings of envelope elements (exterior walls, roof, foundations and slabs). Notes presence of vestibules at building entrances for temperature control.

Interior Finishes

Evaluation of types and conditions of interior wall, flooring, and ceiling finishes.

Rooftop HVAC Equipment

Review of type and apparent condition of roof top units (RTUs), exhaust fans, and air conditioning equipment, if present.

HVAC Controls

Review of types of thermostats and type and apparent condition of Building Management System (BMS) if present.

Kitchen Equipment and Systems (Architectural)

Evaluation of adequacy and apparent condition of kitchen equipment.

Kitchen Equipment and Systems (Electrical)

Observation of electrical kitchen appliances.

Kitchen Equipment and Systems (Plumbing)

Observation of gas kitchen appliances. Observation of apparent condition of kitchen plumbing fixtures, and whether there are separate sinks for handwashing and dishwashing, per health and plumbing codes. Notes if proper fire suppression system exists where required.

Natural Gas Distribution System

Review of apparent condition of the natural gas system, how it enters the building and is distributed, and of shut-off valves.

Generator

Review of type of generator, type of fuel source, and apparent condition if one is present.

Elevator

Evaluation of apparent condition of elevator if present.

Ventilation Distribution Systems

Review of locations and apparent condition of fans, ductwork, duct grilles, and other ventilation components.

Electrical Services

Apparent condition status noted. Review of available capacity, location and appearance of electrical service and meter age.

Life Safety

- » Means of Egress:
 - › (Architectural): Evaluation of apparent existence of proper smoke and/or fire doors, and if mechanical hold-open devices appear in good working condition. Notes if egress paths are direct and unencumbered, and whether there are enough exits relative to the facility population.
 - › (Electrical): Review of illuminated exit signs and whether they are in the proper locations and appear to be in good condition.
- » Fire Protection (Sprinklers): Observation of type and age of system and components. Review of maintenance records and certifications, if available.
- » Fire Alarms: Observation of type, age, and appearance of systems. Review of available testing records.

Security

Entry Sequence: Observes if schools have only a camera/buzzer system at their main entrance or whether the main building entrance is adjacent or near the main office. (Adjacency/proximity of main office to main entrance allows for direct observation of the entire person, as well as control of their movements)

Lighting Quality/Control

Observed (not measured) light levels at the working surface, type of light fixtures and whether they provide an even dispersion and control of light for general academic tasks as well as for use of technology. Apparent condition, locations, and lighting uniformity are noted.

Toilets and Fixtures

Review of locations and apparent conditions of fixtures. Notes the maintenance and cleanliness of fixtures and flow of fixtures.

Plumbing Distribution Systems

Review of piping type, apparent corrosion, and equipment, including presence or absence of water heater & back-flow preventer.

ADA / Accessibility

- » (Architecture): Observes whether the facility is compliant with the Americans with Disabilities Act (ADA) of 1990 standards. Evaluates adequacy and conditions of ramps, lifts, and elevators and whether every occupiable space in the facility can be accessed by anyone with a disability. Other considerations include compliancy of building elements such as clearances and door hardware.
- » (Plumbing): Evaluation of whether toilet facilities and plumbing fixtures are ADA-compliant.

Structural Systems

The assessment team conducted visual inspections to observe signs of deterioration. No exploratory demolition, removing finishes, or viewing above ceilings was conducted. Areas that were hard to reach, off limits, or obscured by other systems that prohibited view of the structure were not assessed. Each of the criteria listed below is considered as it relates to the structural elements of the building.

A “Yes” comment in the assessment indicates that we observed signs of deterioration. A “Not Observed” comment in the assessment indicates that we either did not observe any distress in the structural element or were not able to observe the element due to the aforementioned limitations, and this does preclude an unobserved area from distress.

- » Roof structural framing: As the framing is covered by roofing, observations are usually made from below. Water leaks are a common cause of damage to roof framing and part of the visual assessment is to look for signs of water damage. In wood framed structures, visual signs include mold or rotting wood. In structures with metal deck, visual signs include rusting of the deck and in concrete structures it can be cracks with rust stains or spalled concrete, indicated where a section of concrete has broken off (typically caused by water penetrating concrete through small cracks causing the steel reinforcing to rust and expand putting outward pressure on the concrete and causing it to break off).
- » Floor structural framing: Common signs of deterioration in floors can be cracks in floors finishes (such as terrazzo), cracks in the bottom of concrete slabs or beams, water damage like that in roofs and longitudinal cracks (or checks) in wood framing. Cracks in floor finishes while cosmetically objectionable is not necessarily an indication of a structural failure. There are several causes for cracks in wood framing members (joists or beams) which does not necessarily mean the member is structurally inadequate.
- » Walls/columns: Walls are typically framed with masonry, concrete, or wood or light gage metal studs with varying finishes. Columns typically consist of steel, concrete, or wood posts and can also be masonry piers. Common signs of deterioration in concrete and masonry walls are cracks in the walls. Cracks typically run vertically (bottom to top), although in masonry walls the cracks often follow the mortar joints. Cracks in walls can be caused by many factors: shrinkage in the wall due to changes moisture or temperature, movement of the supporting structure, or stresses in the wall caused by other loads. Concrete columns can have spalled concrete, wood posts can have longitudinal cracks (similar to floor members), and masonry piers can have cracks similar to walls.
- » Foundations: Notes the type of foundation. Some types include shallow spread footings (concrete pads) and deep foundations such as caissons and piles that extend deep into the ground. Foundations generally include concrete components and are located below ground – making the system difficult to observe without performing some excavation. Some common signs of deterioration are cracks in foundation walls and areas where there has been vertical movement, indicating some settlement of the structure over time, which can be common. The causes of the cracks are like those described for walls.
- » Facades: The structural components of the façade are typically the wall structure (see “Walls” above) but can also include the structural framing for overhangs or other horizontal elements that are part of the walls. Like in roof framing, moisture is a common cause for distress in facades. Common signs of distress are spalled concrete, cracks in concrete or masonry walls, and rusting steel members such as angle lintels over window and door openings in masonry walls. Note that some of these signs of deterioration do not necessarily indicate a structural deficiency and may only require maintenance.
- » Identifiable Lateral System: Notes the presence and type of lateral load-resisting system, such as steel braced frames or shear walls consisting of concrete or masonry walls. Often, steel braced frames are imbedded within walls, making them difficult to identify. With masonry walls, it can be difficult to determine if a wall is a shear wall or just a partition wall. It is not possible to determine the structural adequacy of shear walls or braced frames without an in-depth investigation and it should be noted that many masonry walls in older buildings have little or no reinforcing. Common signs of distress in concrete and masonry shear walls are like those described for walls above.

Community Assessment: Building Evaluation

The Community – Building assessment included several categories including historical value, emergency shelter status, and use of community and school within/without the buildings. Historical value reviewed the historic inventory and register status of the building. Because schools are often the largest structure in a neighborhood, the City has designated certain facilities as emergency shelters. Additionally, several schools are directly connected to community centers or utilize adjacent neighborhood facilities for athletics and enrichment. Whether the community utilized the building after hours or on weekends was also considered.

New Hampshire Division of Historical Resources (DHR) Status

Yes/No; Comment, if applicable. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

Inventory of Historic Assets

Yes/No; Comment, if applicable. Notes whether the building is listed on any inventory of historic assets. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

State Register of Historic Places

Yes/No; Comment, if applicable. Notes whether the building is listed on a state Register of Historic Places. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

Locally Designated Historic District

Yes/No; Comment, if applicable. Notes whether the building is within a local historic district. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

Emergency Shelter

Yes/No; Comment, if applicable. Criteria noted and considered as part of the overall community building score. A designation by the city does not certify compliance for all state and federal requirements for the designation.

Community-Use Spaces

Yes/No; Comment, if applicable. These were determined after speaking with school administration during site visits. Community spaces attached to schools were also considered. Criteria noted and considered as part of the overall community building score.

Building Suitability for School Use

Yes/No; Comment, if applicable. Considered any major life-safety concerns for suitability. Criteria will inform opportunities and constraints for modifying the existing building.

Overall Community Building Rating

This is a judgment on the part of the reviewer(s) that considers all aforementioned factors, as well as amenities located in proximity to school sites and access to public transportation.

Facility Assessment: Site Evaluation

The site assessment team performed evaluations at each school facility in the district’s portfolio. These evaluations considered the quality, condition, and capacity of the various exterior spaces of the facility. These spaces included: landscaped, educational, recreational, vehicular and pedestrian areas. This field effort was complimented by a study and research of the sites from web-based resources. The resulting information was then used to guide recommendations regarding maintenance, renovation, and/or replacement.

The diverse scope of site elements for schools varies in their relative impact to education and school operations. Priorities include elements that have large impacts to education and/or incur substantial impact to improve or repair.

- » ADA Accessibility
- » Walkways/Curbs/Sidewalks
- » Play Areas
- » Drainage
- » Parking Quality
- » Drop-Off/Pick-Up Routes
- » Walls & Slopes
- » Site Lighting
- » Fencing
- » Neighborhood Streets
- » Evaluation Criteria

Site Evaluation: Criteria Rating Hierarchy

The site evaluations were judged on a scale as defined below:

- None / Minor: Element is functioning reliably and requires a little repair and routine maintenance.
- Moderate: Element is functioning minimally and requires some repair by a specialist.
- Major: Element is barely functioning and requires substantial repair by a specialist.
- Replace: Element is not functioning correctly and requires total replacement.
- Not Present: Element does not exist or completely failed. This element should be replaced and/or provided. In some instances (parking, walls/slopes and fencing) this element is not required.

Site Evaluation: Physical Analysis Definitions

Parking & Vehicular Circulation

Quality of vehicular area paving and quantity of parking spaces considered. This element may not be required if “Not Present”.

Ground Cover

Presence and condition of landscaping, lawn areas, and any other non-hardscape areas. Ground cover evaluated for aesthetic value, shading, and functionality for outdoor gathering

Fields

Presence and apparent condition of athletic or play fields on the property.

Neighborhood Streets

Connectivity to residential areas surrounding the site. Condition of adjacent/ off-site roadways, sidewalks, and accessible elements considered.

Drop-Off/Pick-Up Routes

Segregation of buses, private vehicles, parking, and neighborhood traffic considered. Both on-site and off-site routes considered. This element may not be required if “Not Present”.

On-Site Walkways/Curbs/Sidewalks

Quality of all pedestrian spaces considered.

ADA Accessibility

Availability, location, and condition of accessible routes considered. The accessible routes connect building entrances, handicap parking, public streets, and site facilities. Accessibility is considered “Not Present” if there is no accessible building entrance.

Site Lighting

Condition, location, and quantity of lighting considered.

Fencing

Condition of fencing and gates of various types considered. This element may not be required if “Not Present”.

Drainage

Surface ponding, water quality structures, and condition of visible infrastructure considered.

Play Structures

Evaluation of apparent condition of play structures and if they are appropriate for range of ages of students at a school, if present.

Walls and slopes

Condition of retaining walls and stabilized slopes considered. This element may not be required if “Not Present”.

Wetlands on site

Yes/no; proximity of wetlands or natural resources to the site, which – if present – may add restrictions or regulatory challenges to site renovations or expansion.

Play Areas

Presence, suitability, and physical condition of casual recreation and play for students. Play structures, surfacing, and courts considered. This element may not be required if “Not Present”.

Outdoor Classrooms

Evaluation of apparent condition of outdoor classrooms or learning areas if present.

Environmental Justice Populations

Review of designation of site and adjacent neighborhoods on the Social Vulnerability Index, per state GIS.

Feasibility of Building Expansion on the Current Site

Evaluation of whether building is capable of appropriately expanding on its current site. Expansion can be horizontal, vertical, or infill, depending on the building's configuration. Feasibility of expansion based on size of property, existing coverage, regulatory restrictions, and physical constraints such as topography and proximity to natural resources.

Feasibility of Site Expansion

Evaluation of whether site expansion is possible, based on adjacent properties, and physical constraints, such as roads, proximity to protected lands, and easements.

Community Assessment: Site Evaluation

The Community – Site assessment included the broad categories of transportation access and neighborhood elements. Transportation access considered the condition of the adjacent streets, the ability of students and adults to bicycle and walk to the school, and the accessibility of public transportation. Neighborhood elements considered the school's proximity to community, civic, educational, commercial, and athletic facilities.

New Hampshire Division of Historical Resources (DHR) Status Inventory of Archeological Assets (Site Review)

Comment, if applicable. Criteria will inform opportunities and constraints for modifying the existing building. In some cases, data may not be available.

School Buses

Review of types and numbers of school buses and bus queuing.

Accessible to Transit

Building is located within 2 blocks (1000 feet) of at least 2 stops on bus lines of regular frequency (at least every 10 minutes, during rush hour and mid-afternoon). Criteria noted and considered as part of the overall community building score.

Bikeable

Facility is considered bikeable if within 2 miles of multiple residential neighborhoods, without riding on busy streets that lack dedicated bike areas. Criteria noted and considered as part of the overall community building score.

- » Wide sidewalks and/or low-traffic streets
- » Adjacent to or within a residential neighborhood, without crossing busy & wide (4+ lanes) streets
- » Not located on a steep street
- » Bike racks are present at the school and are safely accessed from site entry points

Walkable

Facility is considered walkable if within 1.4 miles of residential neighborhoods, with consistent sidewalks, and walking route does not require students to cross busy or dangerous streets (per district eligibility criteria).

- » Consistent, accessible sidewalks with crosswalks
- » Adjacent to or within a residential neighborhood, without crossing wide (4+ lanes) streets

Site suitability for school use?

Yes/No, Comment if applicable. Considers overall site conditions, overall community rating, and size of site.

Overall Building – Community Condition:

This is the professional judgment on the part of the reviewer(s), considering all aforementioned factors and with consideration of nearby neighborhood, community, educational, and athletic facilities. Criteria noted and considered as part of the overall community building score.

Educational Assessment Criteria

Educational Facility Effectiveness Evaluation

Educational Facility Effectiveness of Learning Environments (EFE-LE)

The quality of physical environments has direct impacts on educational outcomes. The EFE analysis considers both inherent building characteristics of physical appearance and condition, and introduced equipment (e.g., furniture and technology). These qualitative factors have a large impact on overall student performance, as they influence students' comfort and ability to concentrate on tasks; teacher and student health and wellness; as well as absenteeism and retention.

Building environments also affect the overall educational effectiveness rating. Fixed elements, such as walls and windows, are components that are not easily remedied and may require extensive or invasive renovation. Other elements, such as furniture or finishes, can be more easily updated, replaced, or supplemented.

Fixed Building Elements include:

- » Ventilation
- » Natural Daylighting
- » Lighting Quality
- » Acoustical
- » Environment (Inviting/Stimulating/Comfortable)
- » Power and Technology Infrastructure
- » Access to water for student projects
- » Access to toilet facilities

Repairing these fixed elements may require buildings to be unencumbered of students (i.e., vacant) for the duration of the work, depending on the upgrades required.

- » Adaptable elements
- » Technology: ubiquitous wireless access for teachers and students and classroom technology
- » Furniture: light weight, ergonomic and supportive of collaboration
- » Finishes
- » Adjacencies of Learning Environments
- » Access to outdoor learning (classrooms or other)

These considerations often consist of singular systems and can be repaired or replaced independent of other systems. They may change frequently with the evolving landscape of educational pedagogy and should support a building that can adapt flexibly at relatively low costs. These upgrades can be executed internally, by facilities personnel or with arranged contracts.

Educational Facility Effectiveness Evaluation: Criteria Rating Hierarchy

The EFE-LE uses the following classification system:

- Excellent: Elements meet needs for 21st century (Next Generation) teaching and learning
- Good: Elements contribute to teaching and learning
- Fair: Elements somewhat interfere with teaching and learning
- Poor: Elements detract from or interfere with teaching and learning
- Deficient: Non-existent or inoperable systems or elements

Educational Facility Effectiveness Evaluation: Analysis Definitions

Evaluation Criteria

Building Originally Designed As: Over time, a school building may have modified the range of grades served. Knowing their original use quickly provides some insight into space types and building appointments.

Best Grade Configuration for this School Building

A school building may be best suited for a different range of grades or use depending on the types, quantities, and sizes of spaces, as well as the existing site attributes, including:

- » Heights of casework, markerboards and other elements the students use
- » Configuration and heights of toilet room fixtures

Ventilation

Fresh air is a critical component for health, wellness, and overall student performance. An even distribution of ventilated air is also important. Different ventilation systems (unit ventilators, central air ventilation, no mechanical ventilation) provide varying levels of outdoor air percentages and filtration. Observe whether mechanical ventilation is provided and what the apparent quality of the ventilation system is. Qualitative measurements are not taken, however visual, olfactory, and thermal observations are made.

Natural Daylighting

Considered to be a better quality of light than artificial lighting. Evaluates the general quantity/quality of the natural light and note if most spaces have access to daylight.

Artificial Lighting Quality

Observed (not measured) light level at the working surface. Type of light fixture and whether it provides an even dispersion of light for general academic tasks, and whether the fixture is dimmable, to accommodate use of technology.

Acoustical

The proper balance between voice reinforcement and sound absorption impacts “speech intelligibility.” This includes both sound performance within the space, as well as sound coming from outside the space. Observe whether the space appears to have appropriate acoustical properties for teaching and learning.

Technology (Power):

There are enough electrical outlets to support a future technology-rich classroom/school and they are properly distributed throughout the space.

Technology (Wireless):

There are sufficient access points throughout the school to support a 1:1 technology environment and fiber optic wiring exists within the building. The main distribution room (server room) is air-conditioned, to ensure system reliability.

Technology (Interactive):

Classrooms and other teaching spaces have working interactive technology, such as interactive marker boards and document cameras.

Furniture

Different educational-delivery models can be reinforced by furniture type and flexibility. Ideal furniture is light and mobile enough to be easily re-arranged in multiple configurations. Furniture is ergonomic, comfortable, in good condition and promotes student collaboration.

Finishes

Materials and conditions of the walls, floors and ceilings. Both physical and aesthetic conditions are considered.

Environment (Inviting/Stimulating/Comfortable)

Evaluates whether building is aesthetically pleasing and if it is a place where students and teachers feel comfortable and want to spend time in each day.

Adjacencies of Learning Environments

Classrooms and other learning environments have a relationship to each other which promotes collaboration, communication, and other aspects of 21st century teaching and learning. Spaces promote interdisciplinary learning.

Outdoor Classrooms

Students have access to outdoor classrooms or other outdoor learning opportunities to learn in different ways, sometimes involving nature and hands-on activities.

Site Components

Playgrounds/Play Areas

Description of play surface materials (hard or soft). Evaluates condition of on-site play structures and whether structures are age-appropriate to the school's student population.

Accessibility

Evaluates conditions of play areas, including the ground surface/material, and whether areas are accessible to children of various disabilities.

Play Fields

Describes conditions of play fields, if present, and whether fields natural grass or synthetic turf.

Flexibility in Building Typology

Evaluates whether the building can serve alternative grade levels or support a special needs-focused curriculum.

Educational Transformation to Support 21st Century Needs

Evaluates if the building's construction easily allows for renovations that may change room sizes, replace or upgrade mechanical and electrical systems, and accommodate alternative educational-delivery methods (e.g., project-based learning [PBL]). This can often be the largest difference between a modern steel-frame building and interior masonry-bearing wall construction.

Building as Swing Space

Assuming the building is otherwise unoccupied, the ability to use the building for educational purposes for the temporary relocation of a school population during a period of renovation or construction.

Utilization Rate

Description of the utilization rate and if it is 85% or higher. For high schools, classroom utilization of 85% are considered at capacity. Rates higher than 85% show levels of overcapacity and overcrowding. Middle schools generally work to a utilization of 90% and elementary schools at near 100%.

Educational Facility Spaces Effectiveness Evaluation

The Educational Facility Effectiveness – Spaces (EFE-S) metric compares the sizes of educational spaces to the New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines for 21st century teaching and learning in new capital projects. This quantitative analysis is important for establishing the level of adequacy of the existing spaces for educational delivery. It also indicates whether a facility is deficient/missing dedicated educational spaces normally found in buildings of its grade level and typology.

Primary considerations often affect core curriculum and include:

- » Classrooms (Depending on typology, these may include Pre-K and Kindergarten)
- » Teacher Planning
- » Small Group
- » Science
- » Art
- » Music
- » Vocations and Technology
- » Media Center
- » Cafeteria

Secondary considerations may allow for district flexibility in programming and community resources outside the traditional building environment, and include:

- » Gymnasium (This program space is sometimes served by local community spaces)
- » Gymnasium Options
- » Auditorium
- » Stage
- » Medical
- » Administration & Guidance
- » Air Conditioned Technology Network Room
- » Other considerations
- » Special Education: Self-Contained
- » Special Education: Resource or Small Group

Note: If a school has a special education program, its quantity of spaces will vary. Also, some substantially separate programs do not require full-size classrooms to be effective. For this reason, special education was considered differently than typical classroom spaces.

Educational Facility Spaces Effectiveness Evaluation: Criteria Rating Hierarchy

The educational facility effectiveness assessment for spaces used a quintile classification hierarchy as defined below:

- Excellent: Exceeds New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines (+10% or greater)
- Good: School facilities are appropriate to house current enrollment and educational program. NSF meets New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines (-10% to +10%)
- Fair: School facilities appear to be adequately sized for current enrollment and educational program. NSF somewhat less than New Hampshire Code of Administrative Rules, Section Ed. 321 (-10% to -20%)
- Poor: School facilities may not be adequately sized for current enrollment and educational program. Net square footage (NSF) at least 20% less than New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines
- Deficient: Dedicated space does not exist.

Educational Facility Spaces Effectiveness Evaluation: Analysis Definitions

Narratives

The team considered the long-term goals relative to each building's capability of supporting Manchester School District's educational vision for 21st century (next generation) learning and teaching.

Engaged Learning

Engaging with the curriculum, applying it to an authentic context. Making connections between content areas and values/curiosity and interest. Finding connections to the community and making a difference. Public and tangible products. There is selective and intentional engagement, and agency in how one keeps focused and takes breaks.

- » The following were criteria used for evaluating the levels of Engaged Learning at each school:
- » The building (is/is not) comfortable to learn in.
- » The building (has/lacks) appropriate temperature control and ventilation.
- » The building (has/lacks) a space that can be used as a flexible learning commons for collaborative learning and presentations.
- » The building (makes use/does not make use) of public space for teaching and learning.
- » The building (provides/lacks) display space for student work to reinforce student accomplishments.
- » The building (provides/lacks) space for teacher collaboration and planning.

Differentiated Learning

Acknowledging different learning styles. Encouraging how to understand one's self (self-knowledge). Flexibility that occurs within instruction, which also promotes flexibility in how students demonstrate learning. The following were criteria used for evaluating the levels of Differentiated Learning at each school:

- » Classrooms (are/are not) large enough to support Universal Design for Learning (UDL), including the ability to create learning zones.
- » The building (has/lacks) breakout spaces for differentiated/personalized learning and special education.
- » The furniture in the building (can be/has difficulty being) flexibly arranged.

Cognitively Demanding Tasks/Programs

- » The classroom environment (is/is not) sufficiently flexible to allow for different teaching and learning styles.
- » Building (supports/lacks) learning environments that support music.
- » Building (supports/lacks) learning environments that support art.
- » Building (supports/lacks) learning environments that support physical activity/education.
- » The building environment (supports/does not support) STEM adequately.
- » The building (provides/lacks) space to experiment, create and collaborate.
- » The building (has/lacks) performance/presentation space.
- » Based on location and proximity to community resources and public transportation, teachers and students (can/have difficulty) access(ing) the City as a learning tool.

Overall EFE Rating

NH Code of Administrative Rules, Section Ed. 321 areas are based on current enrollment within school. Actual areas were determined by measuring CADD plans provided by Manchester School District. SMMA did not field-measure the buildings but verified general conformity with existing conditions by measuring spot values to determine the rough accuracy of CADD drawings. The design team reviewed the 2018 CMK Long-Range Facilities Plan, which informed some of the educational effectiveness ratings.

The following outlines the rating system used for evaluating the Overall Educational Facility Effectiveness:

- Excellent: Elements meet needs for current AND future teaching and learning.
- Good: Elements contribute to teaching and learning.
- Fair: Elements somewhat interfere with teaching and learning.
- Poor: Elements detract from or interfere with teaching and learning.
- Deficient: Non-existent or inoperable systems or elements.

