



**MANCHESTER**  
SCHOOL DISTRICT

# **Weston Elementary School**

Educational and Facilities  
Master Plan

**smma**



# Table of Contents

1. Site Plan
2. Facility Evaluation Criteria
3. Site Evaluation Criteria
4. Educational Assessment
5. Assessment Team Scoring Rubric

## Summary

Included in this report are assets that were collected during the long term facility planning process. Each school's report package contains an At-A-Glance summary report, Facility Evaluation Criteria sheets, and site plan(s). Site plans are included to illustrate the context of the building in relationship to the city, neighborhood, and other adjacent amenities and parcels. The At-A-Glance summary sheets include general information about each school building including school data, such as population and grade structure, etc., site and building data, tax assessor's information, community uses, State of NH Code of Administrative Rules, Operational Data, and Cost model information for repairs and renovations. The Facility Evaluation Criteria sheets are the facility assessment team's findings at each Tier 1 school building including building physical assets, sites, and educational facility effectiveness. On April 24, 2023, the assessment team visited all the Tier 1 school buildings.


SCHOOL NAME

Weston Elementary School

SITE VISIT


August 2023

# At-a-Glance



FA: Building

FA: Site



EFE: Learning

EFE: Spaces



Excellent

Deficient



**Address**

7 Michigan Avenue, Manchester, NH 03104



**Gross Square Footage (GSF)**

61,827 sf



**Grades**

Pre-K–5th Grade



**Site Acreage**

2.77



**Hours of Operation**

8:25am–2:50pm



**Date of Construction**

1922



**2022–2023 Enrollment**

519



**Date of Addition Construction**

1958, 1975

SCHOOL NAME

Weston Elementary School

SITE VISIT

August 2023

# Site Plans



SCHOOL NAME

**Weston Elementary School**

SITE VISIT

**August 2023**





# Facility Evaluation Criteria

Physical Analysis	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
<b>Roof Membrane (Architectural)</b>					
<i>"Roofs were replaced in 2000 with a built-up asphalt roof systems. There are reported roof leaks in many locations. Flashings appear to be failing in several areas. All roofs are beyond their useful lifespan and typical warranty period, so replacement is recommended."</i>					
<b>Existing Photovoltaics</b>					
<i>"N/A"</i>					
<b>Space for Solar on Roof</b>					
<i>"Space on roof is available, exact locations and SF size can be evaluated."</i>					
<b>Façade</b>					
<i>"Masonry veneer generally seems to be in good shape. Several areas of efflorescence and staining of the brick were observed, particularly below window sills. Minor repointing will be required."</i>					
<b>Windows</b>					
<i>"All exterior windows and doors were replaced in 2000 with double-paned aluminum window and storefront systems. Although there is some useful life remaining, the thermal performance is not as efficient as current window systems. Some exterior doors require gasketing and weatherstripping."</i>					
<b>Boilers (Mechanical)</b>					
<i>"The building has two gas-fired hot water boilers that are new in the last 3 years. There is a primary-secondary pumping arrangement where primary pumps have ECM speed controls, and secondary pumps have VFDs."</i>					

Physical Analysis	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
<b>Boilers (Plumbing)</b>	●				
	"Refer to mechanical report for HVAC boilers. Domestic hot water is fed from an electric indirect water heater (119 gallon, Lochinvar Squire Model SIT119DW). The configuration includes a domestic circulator pump (hot water return) and master mixing valve. Manufactured date of 2019. Heater is within unit expected life expectancy."				
<b>Heating Distribution Systems</b>		●			
	"Generally, the piping/insulation are in good condition, but some of the piping/insulation on the roof needs to be replaced. For terminal heating equipment, the building has fin tube radiation in most spaces with exterior envelope and entrances, and back-of-house spaces are heated with unit heaters."				
<b>Building Envelope Thermal Performance</b>			●		
	"The original buildings (1922 and 1958) most likely have not insulation in walls, roofs and under slabs. The 1976 addition has minimal insulation in walls."				
<b>Interior Finishes</b>		●			
	"Interior finishes are generally in good condition. VCT flooring was replaced in several areas in 2005. There are some localized areas of VCT cracking at building expansion joints. Interior casework is generally old and sinks are not accessible. Toilet room finishes are worn and dated in many locations. Although corridor ceilings were updated to ACP in 2005, there are several water-stained areas. Classroom door hardware was recently upgraded."				
<b>Rooftop HVAC Equipment</b>			●		
	"The building has new energy recovery units which provide heated/cooled ventilation air and exhaust. Only classroom-related units are being replaced, there are other older units serving non-classroom spaces that are reaching the end of their useful life. The mobile unit has its own HVAC system that provides both heating and cooling."				
<b>HVAC Controls</b>			●		
	"Building controls are JCI Metasys (district standard). The building uses various types of thermostats, some of which are reaching the end of useful life and should be replaced."				
<b>Technology Infrastructure</b>				●	
	"Bandwidth of fiber optic and copper network cabling is inadequate for School Communications. Telecom Rooms are not adequately secured allowing staff to use them for storage."				

Physical Analysis	● NONE / MINOR	● MODERATE	● MAJOR	● REPLACE	○ N/A
<b>Technology Systems</b>				●	
	"Telephone and WiFi systems are at the end of useful life. Network switches have been recently replaced. Not all Telecom Rooms are air conditioned, leaving equipment vulnerable to overheating."				
<b>Security Systems</b>		●			
	"The City is working with a Security Systems Vendor to deploy 500 CCTV cameras throughout the District's Schools. Adequate bandwidth is a concern for transmitting video. Notification and Lock Down systems are not present. Indoor cellular signal booster system is desired."				
<b>Kitchen Equipment and Systems (Electrical)</b>	●				
	"A few kitchen receptacles were observed non-GFCI type and shall be replaced."				
<b>Kitchen Equipment and Systems (Plumbing)</b>		●			
	"The kitchen plumbing fixtures and equipment appeared in fair condition. The piping below the sinks is mostly exposed copper (chrome coating is recommended. The exposed piping is in fair condition. The equipment includes a dishwasher, prerinse sink, and vitreous china hand washing sink."				
<b>Natural Gas Distribution System</b>	●				
	"Natural gas distribution observations were limited to exposed piping within mechanical rooms and at the exterior service. Refer to the gas service section of this report for exterior observations. Gas is piped to the HVAC boilers. Overall the piping seems to be in good working order."				
<b>Current Fuel Source</b>		●			
	"The building of natural gas services. A 2-inch line comes up from underground and reduces to a 1 1/2-inch regulator. It then increases to a 3-inch meter, The discharge from the meter is a 4-inch main that runs along the building wall and into the building. -The system is assumed to be intermediate pressure based on the meter/regulator assembly. The piping is rusting and replacement during future renovations is recommended."				

**Physical Analysis**

● NONE / MINOR    
 ● MODERATE    
 ● MAJOR    
 ● REPLACE    
 ○ N/A

<b>Generator</b>	<span style="color: yellow;">●</span>			
<p><i>"The existing 12kW/15kVA 120/208v diesel-fired emergency generator is manufactured by Kohler. It's indoor type, installed in the Main Electric room 037 at Ground level. The generator appears old, but in fair operational condition. There are no known issues. A small tank is indoor type, located in Mechanical room adjacent to the room with generator. The generator capacity is very small. It supports only some dedicated emergency lights in the building via an ATS and Emergency panel, both located adjacent to the generator in the Main Electric room. The generator is suggested to be replaced with an outdoor type and skid-based diesel fuel tank. The replaced generator would be of a larger kW capacity in order to support other building loads, such as heating system, communication systems (intercom, data, telephone, etc.), fire alarm panel, refrigeration equipment, etc."</i></p>				
<b>Elevator</b>	<span style="color: yellow;">●</span>			
<p><i>"Due to age of elevator, controls replacement may be required and cab finishes need to be updated."</i></p>				
<b>Ventilation Distribution Systems</b>	<span style="color: yellow;">●</span>			
<p><i>"In classrooms, ventilation is provided by ceiling diffusers; the return air is either low on the wall or in the ceiling. Additionally, classrooms have ceiling fans for comfort. Ductwork is in the process of being replaced, connecting back to mains from units on the roof. In-room air filters are caked with particulate and need filter cleaning/replacement. The building has many exterior louvers, but they no longer appear to be in use for classrooms."</i></p>				
<b>Electrical Services</b>	<span style="color: yellow;">●</span>			
<p><i>"Exterior pad-mounted utility transformer by PSNH is located adjacent to the Main Electric room. It appears in good condition. The utility energy consumption is metered by PSNH on the service's primary side. The utility transformer's secondary feeder is terminated in the Main Distribution panel MDP located in the Main Electric room 037. The Main Distribution panel is manufactured by General Electric. It's rated 1,200 Amp 120/208v 3ph 4w with 1,000 Amp MCB (Main Circuit Breaker). The MDP was installed around year 2004 via Improvements project, and appears now in good operational condition. Panels fed downstream from the MDP are installed throughout the building, both surface- and recessed-mounted. Majority of panels appear "old", and most likely reached the end of their useful life expectancy (about +/- 40 years) and shall be replaced. Also, most of these panels are manufactured by Federal Pacific (FPE) which were discontinued since around 1980, and considered unreliable by experts these days. Power feeders to downstream panels were replaced at the time of the MDP 2004 installation, and shall be in good conditions. Receptacles were upgraded during the same 2004 Improvement project, and appear in good operational condition."</i></p>				

**Physical Analysis**

● NONE / MINOR    
 ● MODERATE    
 ● MAJOR    
 ● REPLACE    
 ○ N/A

<b>Life Safety: Means of Egress (Architectural)</b>	<span style="color: yellow;">●</span>				
<p><i>"Quantity, size and locations of egress components appear to be adequate; however, existing building exits are not accessible as they egress at landing levels. Stair guardrails and handrails do not meet code."</i></p>					
<b>Life Safety: Means of Egress (Electrical)</b>	<span style="color: green;">●</span>				
<p><i>"Emergency lighting is provided along the egress pathways. It consists of self-contained internally lighted LED exit signs, battery units and dedicated lights connected to the emergency generator panel. Emergency lighting throughout is observed in adequate operational condition."</i></p>					
<b>Life Safety: Fire Protection (sprinklers)</b>			<span style="color: orange;">●</span>		
<p><i>"The building is currently protected by a partial automatic sprinkler/standpipe system and domestic water service. . A combination 4-inch fire/water service enters the building and goes through a vertical double check valve assembly before feeding the building sprinkler/standpipe system riser. The city water supply can accommodate the sprinkler system demands (Pump not required). Although sprinklers were present in the 1920's portion of the building, the main part of the school (1970's) has very limited sprinkler protection. The system includes a water motor gong and related drain (appears to be abandoned), electric bell, 2-inch main drain, and a two way Siamese fire department connection at the exterior wall. Standpipes include a 1 1/2-inch fire hose valve (hoses removed), and a 2 1/2-fire department valve at each level. Sprinklers are a mix between older soldered sprinklers and newer glass bulb quick response sprinklers. Standard response sprinklers require replacement (or representative testing) at 50 years. The newer quick response sprinklers require replacement or representative testing at 20 years."</i></p>					
<b>Life Safety: Fire Alarms</b>			<span style="color: orange;">●</span>		
<p><i>"The Fire Alarm (FA) system was designed and installed in 2004, and shows some more recent upgrades. The FA system is manufactured by Notifier and consists of the FACP, remote annunciator, radio master box, smoke and heat detectors, double action pull stations, speaker/strobes and strobe only unit. The Fire Alarm Control Panel (FACP) is located in the Main Electric room 037. The remote annunciator and radio master box are located in the main entrance lobby. The Knox box and FA alarm beacon are provided at the main entrance door. The school building has limited fire protection system (sprinkler heads were observed in the old building areas only) and therefore there shall be a "full coverage smoke detection" which is not currently present. The following smoke detection status was observed: Corridors have smoke detectors. All classrooms, all bathrooms, administration area spaces (including the work room containing electrical panel), gym, kitchen, storage rooms, etc. - no smoke or heat detectors were observed in these spaces. Smoke detection devices shall be added in all areas for "full coverage" concept and connected to FACP. The FA signaling devices were not observed in any Administration area spaces, and shall be added and connected to FACP as well."</i></p>					

**Physical Analysis**

● NONE / MINOR    
 ● MODERATE    
 ● MAJOR    
 ● REPLACE    
 ○ N/A

<b>Security: Entry Sequence</b>	<span style="color: yellow;">●</span>				
<i>"The main entrance has controlled card access and an intercom system. There is limited direct visual access to the exterior from the main office. The entrance to the main office is beyond the main entry vestibule."</i>					
<b>Lighting Quantity / Control</b>	<span style="color: green;">●</span>				
<i>"Lighting throughout the building was recently upgraded with 2'x4' LED "basket reflector" type lights equipped with integral occupancy sensors. New LED pendant lights with occupancy sensors were installed in gym. All lights appear in good operational condition. In general, illumination levels throughout the building were observed to be adequate."</i>					
<b>Toilets and Fixtures</b>		<span style="color: yellow;">●</span>			
<i>"Fixtures are in fair to poor condition and are outdated. Major renovations should include replacing fixtures with new low flow fixtures. (sustainability requirements). A bottle filler water fountain has replaced existing drinking fountains."</i>					
<b>Plumbing Distribution Systems</b>		<span style="color: yellow;">●</span>			
<i>"A 2-inch domestic water service splits off from the combined fire/water service. The cold water flows through a 2-inch meter with a 2-inch bypass. A 2-inch reduced pressure backflow preventer is located on the downstream side of the meter. The age of the copper piping throughout the building varies. Piping greater than 40 years old (lifespan 40-50 years) should be evaluated (sample destructive testing, water quality testing) to determine the condition and help estimate the longevity left in the piping. Original valves and pipe solder pre-date current lead free regulations and requirements. Exposed sanitary and storm piping within the looks ok. The condition of the interior of the piping is not known. The expected lifespan of cast iron piping is 50 years. Therefore, original cast iron piping should be scoped/tested to confirm the expectancy left in the piping."</i>					
<b>Accessibility (Architectural)</b>			<span style="color: orange;">●</span>		
<i>"Not all building exits are accessible as they exit at stair landing levels. Not all toilet rooms are accessible. Where accessible toilet stalls are provided in several areas, those spaces still do not provide the wheelchair turning radius or required door clearances. Classroom toilet rooms and sinks are not accessible. Stage in the Gymnasium is not accessible."</i>					
<b>Accessibility (Plumbing)</b>			<span style="color: orange;">●</span>		
<i>"Some fixtures do not meet ADA requirements."</i>					

### Structural Systems: Signs of Deterioration Observed?

	YES	NO	
<b>Roof</b>		X	
	<i>"Bar joist roof with tectum panels supported on CMU bearing walls. From what could be seen the Tectum panels appear to be in good condition."</i>		
<b>Floor</b>		X	
	<i>"Floors appear in sound condition at slab on grade and at upper floors. There is little to no cracking or settlement."</i>		
<b>Walls / Columns</b>		X	
	<i>"Interior CMU masonry walls at corridors and classroom demising walls."</i>		
<b>Foundations</b>		X	
	<i>"Foundation in good condition. No major issues noted."</i>		
<b>Façade</b>	✓		
	<i>"Exterior masonry in very good condition."</i>		
<b>Is Lateral System Identifiable?</b>	✓		
	<i>"Lateral system includes unreinforced, (assumed), masonry walls. No other system noticeable."</i>		











### Community




	YES	NO	
<b>Emergency Shelter</b>	✓		
	<i>"Long Term and Short Term Shelter."</i>		
<b>Are there Separate Community / Non-School Spaces on Site?</b>		X	
	<i>"N/A"</i>		



# Site Evaluation Criteria

Physical Analysis	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
<b>Parking Capacity</b>					
	<i>"Approx. 50 spaces on site, plus 4 additional spots designated for school use on adjacent gas station property. 56 staff per district website. Parking not adequate for staff and visitors."</i>				
<b>Parking Quality</b>					
	<i>"Front parking and drop off loop in process of repaving."</i>				
<b>Ground Cover</b>					
	<i>"Some trees and plantings around the side. Minimal shading or screening from adjacent commercial areas."</i>				
<b>Fields</b>					
	<i>"No fields on site or within walking distance."</i>				
<b>Neighborhood Streets</b>					
	<i>"Front entrance along busy commercial road. Residential streets abutting sides and rear of site."</i>				
<b>Drop-off / Pick-up Routes</b>					
	<i>"One way bus drop off loop at front entrance (with staff parking), car drop off from pull off area along residential street at rear of site."</i>				
<b>Walkways / Curbs / Sidewalks</b>					
	<i>"Bituminous walkways around perimeter of site in mostly poor condition. Concrete walk/plaza at front entrance in good condition."</i>				
<b>ADA Accessibility</b>					
	<i>"ADA spaces and accessible entrance at front of the building. Accessible entrances from bituminous play lot at rear of building. Some inaccessible entrances at side of building."</i>				

<b>Physical Analysis</b>	 NONE / MINOR	 MODERATE	 MAJOR	 REPLACE	 N/A
<b>Site Lighting (Civil)</b>					
	<i>"Building mounted light fixtures."</i>				
<b>Site Lighting (Electrical)</b>					
	<i>"Exterior building-mounted lighting consists of a mix of "older" (seem to have HPS lamps) and new LED type wall packs - they appear in good operational condition. The "older" lights are recommended for replacement with energy-efficient LED lights."</i>				
<b>Fencing</b>					
	<i>"Fencing around rear play area/ lot with gated entrances."</i>				
<b>Drainage</b>					
	<i>"Some (not many) catch basins. Evidence of erosion where runoff overflows off back of site from bituminous play lot low point."</i>				
<b>Play Areas</b>					
	<i>"Bituminous play lot with basketball hoops and two play structures at rear of building."</i>				
<b>Monuments and Memorials</b>					
	<i>"None observed at this site."</i>				
<b>Walls / Slopes</b>					
	<i>"School finish floor elevation higher than most of the surrounding streets, with mild vegetated slopes up along front and sides of the building. Concrete cheek wall around outdoor classroom area in decent condition."</i>				

<b>Physical Analysis</b>	YES	NO
<b>Are there any Wetlands on Site?</b>		
	<i>"No wetlands per GIS or evidence of potential wetlands per site assessment."</i>	
<b>Are there any Easements on Site?</b>		
	<i>"No easements per GIS. Possible easement/ space rental/ agreement regarding parking spaces on adjacent gas station lot."</i>	
<b>Are Play Structures Age-Appropriate?</b>		
	<i>"Play structure is age-appropriate."</i>	

**Physical Analysis**

	YES	NO	
<b>Is there an Outdoor-Learning Area?</b>	✓		
	<i>"Area with picnic tables separated from street by painted concrete retaining wall."</i>		
<b>Should there be a Question on Environmental Justice Populations / Vulnerable Populations?</b>		✗	
	<i>"NH GIS designates site as "Medium" Social Vulnerability Index, based on census analysis."</i>		
<b>Is the Building Expandable on the Current Site?</b>	✓		
	<i>"Building could expand into large bituminous play lot at rear of site, or additional modulars could be added."</i>		
<b>Is the Site Expandable?</b>		✗	
	<i>"School and paved areas fill entirety of site."</i>		

**Community Analysis**

	YES	NO	
<b>Historical Commission Status: Inventory of Archaeological Assets (Site Review)</b>		✗	
	<i>"The site is not listed on the National Register of Historic Places (per the National Park Service website) nor the New Hampshire State Register of Historic Places (per the New Hampshire Division of Historical Resources website). The site is also not within the Manchester Historic District or listed as a locally-designated historic site, per Manchester GIS."</i>		
<b>Are there School Buses?</b>	✓		
	<i>"3 MTA buses and 5 SPED buses, per bus counts provided by the district."</i>		
<b>Bikeable?</b>		✗	
	<i>"No bike racks or designated bike lanes on surrounding streets."</i>		
<b>Walkable?</b>		✗	
	<i>"Sidewalk along Hanover St, but high traffic and proximity of highway present safety concerns and limit the site walkability. Smaller, residential streets to the north, west, and east of site; however, many do not have sidewalks. Not very walkable for elementary age students."</i>		

Traffic Analysis	NONE / MINOR	MODERATE	MAJOR	REPLACE	N/A
<b>Bike Facilities</b> Hanover St	●				
<i>"Consideration may be given to striping a bike lane as Hanover Street is a wide roadway with a 30-mph posted speed limit."</i>					
<b>Bus Stops</b> Hanover St and Beaver St	●				
<i>"No indication of MTA Bus 2 stop in westbound direction."</i>					
<b>Parking</b> Parking lot	●				
<i>"Four accessible parking spaces with curb-free access to main entrance. Inconsistent accessible parking sign height."</i>					
<b>Sidewalks</b> Beaver St	●				
<i>"Sidewalk on west (school) side in poor to fair condition. Cross-slope at playground gate driveway."</i>					
<b>Sidewalks</b> Briar Ave	●				
<i>"No consistent sidewalk. Sidewalk on western half of south (school) side in fair condition. Dirt and gravel underneath playground pavement washing into sidewalk at west end of parking bay on south side of Briar Ave."</i>					
<b>Sidewalks</b> Hanover St	●				
<i>"Sidewalk on north (school) side in poor to fair condition. Gap in sidewalk on south side."</i>					
<b>Unsignalized Intersections</b> Beaver St at Briar Ave			●		
<i>"No crosswalk or detectable warning panels across Briar Ave. NW corner has no curb ramp. Pedestrian crossing should be evaluated for ADA compliancy. No STOP sign on Briar Ave approach."</i>					

SCHOOL NAME

**Weston Elementary School**

SITE VISIT










**August 2023**

REPORT TYPE

**Site Evaluation**

**Traffic Analysis**

 NONE / MINOR    
  MODERATE    
  MAJOR    
  REPLACE    
  N/A

					
<b>Unsignalized Intersections</b> Hanover St at Beaver St					
<p><i>“Crosswalk on north side but no crosswalk on south side. No crossing across Hanover St to connect school with eastbound MTA Bus 2 stop. NE corner has no curb ramp. Curbs in poor condition. No detectable warning panels on the curb ramps and pedestrian crossing should be evaluated for ADA compliancy. This location should be prioritized because it is adjacent to the school and because it is an MTA Bus 2 stop.”</i></p>					
<b>Unsignalized Intersections</b> Hanover St at Michigan Ave/Dunkin’ Driveway					
<p><i>“Crosswalks on north, east, and south sides. Curb ramps on SE and SW corners have detectable warning panels. Curb ramps on NE and NW corners have no detectable warning panels. Pedestrian crossings should be evaluated for ADA compliancy. Crosswalk striping on north side is very faded. East crosswalk has school crossing signs but is very long with limited visibility from east due to parking lane near crosswalk. A bulbout and/or RRFB should be considered for the east crosswalk. The east crosswalk should be prioritized as it is the only crosswalk across Hanover St in front of the school. South crosswalk is also long and could benefit from median between driveways being extended beyond crosswalk.”</i></p>					
<b>Unsignalized Intersections</b> Michigan Ave at Briar Ave					
<p><i>“No crosswalks, despite SE curb ramp which does not have a detectable warning panel. Pedestrian crossings should be evaluated. No STOP sign on Briar Ave approach.”</i></p>					
<b>Unsignalized Intersections</b> Michigan Ave at Parking lot driveway					
<p><i>“Sidewalk material continuous across driveway. No crosswalk or detectable warning panels across driveway. Pedestrian crossing should be evaluated for ADA compliancy. Entrance only sign is not angled perpendicular to Michigan Ave.”</i></p>					



# Educational Facility Effectiveness: Learning Environments (EFE: LE)

## Grade Levels

Building Originally Designed as:	1st Grade–6th Grade
Which Educational Program are you Assessing?	Pre-K–4th Grade
The Grade Configuration this School is Best Suited to:	1st Grade–4th Grade

## Educational Building Analysis

	● GOOD	● FAIR	● POOR	● DEFICIENT	● FAILING
Acoustical		●			
Adjacencies of Learning Environments	●				
Environment (Inviting / Stimulating / Comfortable)			●		
Finishes		●			
<i>"VCT flooring, finishes are tired."</i>					
Furniture			●		
<i>"Furniture is not conducive for flexible arrangements."</i>					
Lighting Quality		●			
<i>"Mix of old fluorescent and new LED."</i>					
Natural Daylighting		●			
<i>"Corridors are dark."</i>					

**Educational Building Analysis**

GOOD FAIR POOR DEFICIENT FAILING

<b>Outdoor Classrooms</b>					●
<i>"None observed."</i>					
<b>Technology: Power</b>		●			
<b>Technology: Wireless</b>		●			
<b>Ventilation</b>	●				
<i>"New HVAC system installed over summer. Some issues Currently but appears to work well otherwise."</i>					

**This Site Includes:**

YES NO

<b>Accessible</b>		✗	
<b>Play Fields</b>		✗	
<b>Playgrounds / Areas</b>	✓		
<i>"Little to no shade provided, ground is mostly hard surface/asphalt."</i>			

**Building Assessment**

YES NO

<b>Can the Building Change Typology Easily?</b>		✗	
<b>Can the Building be Transformed Educationally to Serve 21st Century Needs?</b>	✓		
<i>"Yes, with significant renovations."</i>			
<b>Can the Building Serve as Swing Space?</b>	✓		
<b>Is the Building between 85%–115% Utilization Rate?</b>	✓		



















# Educational Facility Effectiveness: Spaces (EFE)

Space Assessment	QUANTITY	ACTUAL AREA (SF)	MORE INFO
<b>Administration and Guidance</b> (Quantity Varies)	Varies	1760	
<b>Art Classroom</b> (Min Area 900 sf or 36 sf / Student)	1	900	
<b>Cafeteria</b> (Min Area 12-15 sf / Student for Max Number of Diners per Lunch Period)	1	3890	LUNCH PERIODS: 3
<i>"Shared with Gymnasium."</i>			
<b>Classroom: General Education</b> (Min Area 900 sf or 36 sf / Student)	16	625, 630, 875, 890, 900	
<b>Faculty Lounge</b>	2	240, 340	
<b>Gymnasium</b> (Min Area 6000 sf)	1	(see Cafeteria)	STAGE: Yes
<i>"Shared with Cafeteria. Stage used for storage."</i>			
<b>Kindergarten</b> (Min Area 1000 sf or 50 sf / Student)	3	900, 950, 975	TOILET ROOM: Yes
<b>Media Center</b> (Min Area 1800 sf or 4 sf / Student x Design Capacity)	1	2095	
<b>Music Classroom</b> (Area 1200 sf)	1	700	
<i>"In portable."</i>			
<b>Pre-K0/K1</b> (Min Area 1000 sf or 50 sf / Student)	5	525, 875, 900	
<i>"2 self contained (autism) 3 integrated. Half day."</i>			

**Space Assessment**

	QUANTITY	ACTUAL AREA (SF)	MORE INFO
Special Education: Resource of Small Group (Area 500 sf)	3	240, 300, 360	
Special Education: Self Contained (Area 950 sf)	2	900	TOILET ROOM: Yes
Stage (Area 1000 sf)	1	780	
<i>"Used for storage."</i>			
Teacher Planning	1	120	
Technology Lab	1	890	
<i>"Learning Lab"</i>			

**Adequacy of Rooms**

	 GOOD	 FAIR	 POOR	 DEFICIENT	 FAILING
Administration and Guidance					
Art Classroom					
Cafeteria					
Classroom: General Education					
Faculty Lounge					
Gymnasium					
<i>"Undersized, shared with Cafeteria."</i>					
Kindergarten (K2)					
<i>"Undersized"</i>					
Media Center					
Medical					
Music Classroom					
<i>"In portable. Shared with health."</i>					
Pre-K0/K1					
<i>"Undersized"</i>					

**Adequacy of Rooms**

GOOD FAIR POOR DEFICIENT FAILING

	GOOD	FAIR	POOR	DEFICIENT	FAILING
Special Education: Resource of Small Group		●			
Special Education: Self Contained			●		
<i>"Significantly undersized - no dedicated toilet rooms."</i>					
Stage				●	
<i>"Used for storage."</i>					
Teacher Planning			●		

**Special Education Assessment**

YES NO

	YES	NO
18+		×
Autism Spectrum	✓	
<i>"2 PK classroom"</i>		
Cognitively Impaired		×
Deaf and Hard of Hearing		×
Emotional Disturbance		×
English Learners	✓	
<i>"Pull-Out and Push-In"</i>		
Intellectual Disability		×
Life Skills		×
Medically Fragile		×
PT/OT/Speech	✓	
Reset Program		×
Social Emotional		×
Title 1		×

# Assessment Team Scoring Rubric

## Educational and Facilities Assessment Approach

### Assessment Criteria

Educational and Facilities Assessment (E+FA) Approach - Led by architects, engineers, and educational planners from SMMA and its consultants, and in partnership with each school principal, the team conducted both a facility assessment (to take inventory of the building layout and condition) and an educational assessment (to determine the adequacy of spaces for the educational programs offered) in each building. The following report outlines the team organization, methodology and approach taken to assess the Manchester Public School portfolio over the Spring and Summer of 2023.

### Overall Assessment

Categories and criteria were strategically selected for assessment based on stated objectives, past experience, and nature of the Manchester School District portfolio of buildings. Ultimately, the E+FA team created a customized “Manchester School District methodology” which encompassed approximately 75 areas of criteria, organized either facility or site categories that examined physical components, as well as community components.

# Facility Assessment Criteria

## Facility Assessment: Building Evaluation

Facilities varying in terms of age, design, construction methods, and materials were reviewed to determine the condition of the district's portfolio. Building assessments were performed to determine existing components and/or systems' conditions at a specific point in time. The resulting information was then used to guide recommendations regarding maintenance, renovation, and/or replacement. The assessment team conducted visual inspections to observe signs of deterioration. No exploratory demolition, removing finishes, or viewing above ceilings was conducted. Areas that were hard to reach, off limits, or obscured by other systems that prohibited view of the some building components were not assessed. Systems and categories that were assessed included:

- » Building Envelope
  - › Roof Membrane
  - › Facade
  - › Windows
  - › Thermal Performance
- » Boilers
- » Heating Distribution
- » Interior Finishes
- » Rooftop HVAC Equipment
- » HVAC Controls
- » Kitchen Equipment and Systems
- » Natural Gas Distribution
- » Generator
- » Elevator
- » Ventilation Distribution Systems
- » Electrical Service
- » Life Safety:
  - › Means of Egress
  - › Fire Alarm
  - › Fire Protection: Sprinklers
- » Security: Entry Sequence
- » Lighting Quantity/ Control
- » Toilets and Fixtures
- » Plumbing Distribution Systems
- » ADA/Accessibility
- » Structural Systems (consisting of the following components):
  - › Roof framing: This is the horizontal framing consisting of decking, slabs, joists, beams, trusses, etc.
  - › Floor framing: This is the horizontal framing consisting of decking, slabs, joists, beams, trusses, etc.
  - › Walls and columns: These are the vertical elements that hold up the floors and roof structures.
  - › Foundations: Foundations occur at the base of the building and transfer the weight of the building onto the underlying soils.
  - › Facades: These are the outside walls of the building including many non-structural elements (doors, windows, insulation, vapor barriers, etc.) that are part of the weather enclosure for the building.
- » Lateral System: The lateral system in a building is the structural system that keeps the building from falling over when it is subjected to horizontal loads such as wind and earthquake forces.

## Building Evaluation: Criteria Rating Hierarchy

The facility assessment building evaluations used a quintile classification hierarchy as defined below:

- None / Minor: System or element functioning reliably; routine maintenance and repair is needed.
- Moderate: System or element functioning minimally. Repair or replacement of some components is needed.
- Major: System or element is barely functioning. Repair or replacement of most components is needed.
- Replace: System or element is non-functioning, not functioning as designed, or is unreliable. Total replacement all components is needed.
- Not Present: System or element is non-existent, non-functioning, not functioning as designed, or is unreliable. Replacement is needed.

## Building Evaluation: Physical Analysis Definitions

### **Roof**

Roof Membrane: Apparent condition status noted for the roofing material and flashings. Note any obvious deterioration.

### **Existing Photovoltaics**

Yes / No: Criteria noted. However, presence or absence of photovoltaic did not impact overall building condition.

### **Space for Solar**

Yes / No: Comments, if applicable. Evaluation of whether roof space exists for solar (if there are relatively flat areas for possible future solar panels). Note that the roof structure was not evaluated for structural capacity of future PV panels. Criteria noted; however, presence or absence of photovoltaic panels did not impact overall building condition.

### **Façade**

Description of apparent condition and materials of the exterior walls. Observations of any spalling or disintegration of brick or concrete masonry unit (CMU) walls and the condition of the mortar. Notes if there is any obvious movement or structural cracking, and if there is failure, the percentage of failure. With prefabricated panel system facades, notes the types and apparent conditions of attachment systems, panel material, and whether there is deterioration of the surface or caulking or movement in the panels.

### **Windows**

Description of types and apparent conditions of exterior windows. Considers whether most windows appear to be in good working condition, if windows are transparent or translucent, and if they are single or double-paned.

### **Boilers (Mechanical)**

Review of fuel sources and apparent conditions of boilers.

### **Boilers (Plumbing)**

Observation of heating media (e.g. water or steam) of boilers.

### **Heating Distribution Systems**

Evaluation of type and apparent conditions of piping, type, and apparent corrosion.

***Building Envelope Thermal Performance***

Review of the existing drawings of envelope elements (exterior walls, roof, foundations and slabs). Notes presence of vestibules at building entrances for temperature control.

***Interior Finishes***

Evaluation of types and conditions of interior wall, flooring, and ceiling finishes.

***Rooftop HVAC Equipment***

Review of type and apparent condition of roof top units (RTUs), exhaust fans, and air conditioning equipment, if present.

***HVAC Controls***

Review of types of thermostats and type and apparent condition of Building Management System (BMS) if present.

***Kitchen Equipment and Systems (Architectural)***

Evaluation of adequacy and apparent condition of kitchen equipment.

***Kitchen Equipment and Systems (Electrical)***

Observation of electrical kitchen appliances.

***Kitchen Equipment and Systems (Plumbing)***

Observation of gas kitchen appliances. Observation of apparent condition of kitchen plumbing fixtures, and whether there are separate sinks for handwashing and dishwashing, per health and plumbing codes. Notes if proper fire suppression system exists where required.

***Natural Gas Distribution System***

Review of apparent condition of the natural gas system, how it enters the building and is distributed, and of shut-off valves.

***Generator***

Review of type of generator, type of fuel source, and apparent condition if one is present.

***Elevator***

Evaluation of apparent condition of elevator if present.

***Ventilation Distribution Systems***

Review of locations and apparent condition of fans, ductwork, duct grilles, and other ventilation components.

***Electrical Services***

Apparent condition status noted. Review of available capacity, location and appearance of electrical service and meter age.

### ***Life Safety***

- » Means of Egress:
  - › (Architectural): Evaluation of apparent existence of proper smoke and/or fire doors, and if mechanical hold-open devices appear in good working condition. Notes if egress paths are direct and unencumbered, and whether there are enough exits relative to the facility population.
  - › (Electrical): Review of illuminated exit signs and whether they are in the proper locations and appear to be in good condition.
- » Fire Protection (Sprinklers): Observation of type and age of system and components. Review of maintenance records and certifications, if available.
- » Fire Alarms: Observation of type, age, and appearance of systems. Review of available testing records.

### ***Security***

Entry Sequence: Observes if schools have only a camera/buzzer system at their main entrance or whether the main building entrance is adjacent or near the main office. (Adjacency/proximity of main office to main entrance allows for direct observation of the entire person, as well as control of their movements)

### ***Lighting Quality/Control***

Observed (not measured) light levels at the working surface, type of light fixtures and whether they provide an even dispersion and control of light for general academic tasks as well as for use of technology. Apparent condition, locations, and lighting uniformity are noted.

### ***Toilets and Fixtures***

Review of locations and apparent conditions of fixtures. Notes the maintenance and cleanliness of fixtures and flow of fixtures.

### ***Plumbing Distribution Systems***

Review of piping type, apparent corrosion, and equipment, including presence or absence of water heater & back-flow preventer.

### ***ADA / Accessibility***

- » (Architecture): Observes whether the facility is compliant with the Americans with Disabilities Act (ADA) of 1990 standards. Evaluates adequacy and conditions of ramps, lifts, and elevators and whether every occupiable space in the facility can be accessed by anyone with a disability. Other considerations include compliancy of building elements such as clearances and door hardware.
- » (Plumbing): Evaluation of whether toilet facilities and plumbing fixtures are ADA-compliant.

### ***Structural Systems***

The assessment team conducted visual inspections to observe signs of deterioration. No exploratory demolition, removing finishes, or viewing above ceilings was conducted. Areas that were hard to reach, off limits, or obscured by other systems that prohibited view of the structure were not assessed. Each of the criteria listed below is considered as it relates to the structural elements of the building.

A “Yes” comment in the assessment indicates that we observed signs of deterioration. A “Not Observed” comment in the assessment indicates that we either did not observe any distress in the structural element or were not able to observe the element due to the aforementioned limitations, and this does preclude an unobserved area from distress.

- » Roof structural framing: As the framing is covered by roofing, observations are usually made from below. Water leaks are a common cause of damage to roof framing and part of the visual assessment is to look for signs of water damage. In wood framed structures, visual signs include mold or rotting wood. In structures with metal deck, visual signs include rusting of the deck and in concrete structures it can be cracks with rust stains or spalled concrete, indicated where a section of concrete has broken off (typically caused by water penetrating concrete through small cracks causing the steel reinforcing to rust and expand putting outward pressure on the concrete and causing it to break off).
- » Floor structural framing: Common signs of deterioration in floors can be cracks in floors finishes (such as terrazzo), cracks in the bottom of concrete slabs or beams, water damage like that in roofs and longitudinal cracks (or checks) in wood framing. Cracks in floor finishes while cosmetically objectionable is not necessarily an indication of a structural failure. There are several causes for cracks in wood framing members (joists or beams) which does not necessarily mean the member is structurally inadequate.
- » Walls/columns: Walls are typically framed with masonry, concrete, or wood or light gage metal studs with varying finishes. Columns typically consist of steel, concrete, or wood posts and can also be masonry piers. Common signs of deterioration in concrete and masonry walls are cracks in the walls. Cracks typically run vertically (bottom to top), although in masonry walls the cracks often follow the mortar joints. Cracks in walls can be caused by many factors: shrinkage in the wall due to changes moisture or temperature, movement of the supporting structure, or stresses in the wall caused by other loads. Concrete columns can have spalled concrete, wood posts can have longitudinal cracks (similar to floor members), and masonry piers can have cracks similar to walls.
- » Foundations: Notes the type of foundation. Some types include shallow spread footings (concrete pads) and deep foundations such as caissons and piles that extend deep into the ground. Foundations generally include concrete components and are located below ground – making the system difficult to observe without performing some excavation. Some common signs of deterioration are cracks in foundation walls and areas where there has been vertical movement, indicating some settlement of the structure over time, which can be common. The causes of the cracks are like those described for walls.
- » Facades: The structural components of the façade are typically the wall structure (see “Walls” above) but can also include the structural framing for overhangs or other horizontal elements that are part of the walls. Like in roof framing, moisture is a common cause for distress in facades. Common signs of distress are spalled concrete, cracks in concrete or masonry walls, and rusting steel members such as angle lintels over window and door openings in masonry walls. Note that some of these signs of deterioration do not necessarily indicate a structural deficiency and may only require maintenance.
- » Identifiable Lateral System: Notes the presence and type of lateral load-resisting system, such as steel braced frames or shear walls consisting of concrete or masonry walls. Often, steel braced frames are imbedded within walls, making them difficult to identify. With masonry walls, it can be difficult to determine if a wall is a shear wall or just a partition wall. It is not possible to determine the structural adequacy of shear walls or braced frames without an in-depth investigation and it should be noted that many masonry walls in older buildings have little or no reinforcing. Common signs of distress in concrete and masonry shear walls are like those described for walls above.

# Community Assessment: Building Evaluation

The Community – Building assessment included several categories including historical value, emergency shelter status, and use of community and school within/without the buildings. Historical value reviewed the historic inventory and register status of the building. Because schools are often the largest structure in a neighborhood, the City has designated certain facilities as emergency shelters. Additionally, several schools are directly connected to community centers or utilize adjacent neighborhood facilities for athletics and enrichment. Whether the community utilized the building after hours or on weekends was also considered.

## ***New Hampshire Division of Historical Resources (DHR) Status***

Yes/No; Comment, if applicable. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

## ***Inventory of Historic Assets***

Yes/No; Comment, if applicable. Notes whether the building is listed on any inventory of historic assets. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

## ***State Register of Historic Places***

Yes/No; Comment, if applicable. Notes whether the building is listed on a state Register of Historic Places. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

## ***Locally Designated Historic District***

Yes/No; Comment, if applicable. Notes whether the building is within a local historic district. Criteria will inform opportunities and constraints for modifying the existing building to meet changing physical demands for a 21st century learning environment.

## ***Emergency Shelter***

Yes/No; Comment, if applicable. Criteria noted and considered as part of the overall community building score. A designation by the city does not certify compliance for all state and federal requirements for the designation.

## ***Community-Use Spaces***

Yes/No; Comment, if applicable. These were determined after speaking with school administration during site visits. Community spaces attached to schools were also considered. Criteria noted and considered as part of the overall community building score.

## ***Building Suitability for School Use***

Yes/No; Comment, if applicable. Considered any major life-safety concerns for suitability. Criteria will inform opportunities and constraints for modifying the existing building.

## ***Overall Community Building Rating***

This is a judgment on the part of the reviewer(s) that considers all aforementioned factors, as well as amenities located in proximity to school sites and access to public transportation.

# Facility Assessment: Site Evaluation

The site assessment team performed evaluations at each school facility in the district’s portfolio. These evaluations considered the quality, condition, and capacity of the various exterior spaces of the facility. These spaces included: landscaped, educational, recreational, vehicular and pedestrian areas. This field effort was complimented by a study and research of the sites from web-based resources. The resulting information was then used to guide recommendations regarding maintenance, renovation, and/or replacement.

The diverse scope of site elements for schools varies in their relative impact to education and school operations. Priorities include elements that have large impacts to education and/or incur substantial impact to improve or repair.

- » ADA Accessibility
- » Walkways/Curbs/Sidewalks
- » Play Areas
- » Drainage
- » Parking Quality
- » Drop-Off/Pick-Up Routes
- » Walls & Slopes
- » Site Lighting
- » Fencing
- » Neighborhood Streets
- » Evaluation Criteria

## Site Evaluation: Criteria Rating Hierarchy

The site evaluations were judged on a scale as defined below:

- None / Minor: Element is functioning reliably and requires a little repair and routine maintenance.
- Moderate: Element is functioning minimally and requires some repair by a specialist.
- Major: Element is barely functioning and requires substantial repair by a specialist.
- Replace: Element is not functioning correctly and requires total replacement.
- Not Present: Element does not exist or completely failed. This element should be replaced and/or provided. In some instances (parking, walls/slopes and fencing) this element is not required.

## Site Evaluation: Physical Analysis Definitions

### ***Parking & Vehicular Circulation***

Quality of vehicular area paving and quantity of parking spaces considered. This element may not be required if “Not Present”.

### ***Ground Cover***

Presence and condition of landscaping, lawn areas, and any other non-hardscape areas. Ground cover evaluated for aesthetic value, shading, and functionality for outdoor gathering

**Fields**

Presence and apparent condition of athletic or play fields on the property.

**Neighborhood Streets**

Connectivity to residential areas surrounding the site. Condition of adjacent/ off-site roadways, sidewalks, and accessible elements considered.

**Drop-Off/Pick-Up Routes**

Segregation of buses, private vehicles, parking, and neighborhood traffic considered. Both on-site and off-site routes considered. This element may not be required if “Not Present”.

**On-Site Walkways/Curbs/Sidewalks**

Quality of all pedestrian spaces considered.

**ADA Accessibility**

Availability, location, and condition of accessible routes considered. The accessible routes connect building entrances, handicap parking, public streets, and site facilities. Accessibility is considered “Not Present” if there is no accessible building entrance.

**Site Lighting**

Condition, location, and quantity of lighting considered.

**Fencing**

Condition of fencing and gates of various types considered. This element may not be required if “Not Present”.

**Drainage**

Surface ponding, water quality structures, and condition of visible infrastructure considered.

**Play Structures**

Evaluation of apparent condition of play structures and if they are appropriate for range of ages of students at a school, if present.

**Walls and slopes**

Condition of retaining walls and stabilized slopes considered. This element may not be required if “Not Present”.

**Wetlands on site**

Yes/no; proximity of wetlands or natural resources to the site, which – if present – may add restrictions or regulatory challenges to site renovations or expansion.

**Play Areas**

Presence, suitability, and physical condition of casual recreation and play for students. Play structures, surfacing, and courts considered. This element may not be required if “Not Present”.

**Outdoor Classrooms**

Evaluation of apparent condition of outdoor classrooms or learning areas if present.

### ***Environmental Justice Populations***

Review of designation of site and adjacent neighborhoods on the Social Vulnerability Index, per state GIS.

### ***Feasibility of Building Expansion on the Current Site***

Evaluation of whether building is capable of appropriately expanding on its current site. Expansion can be horizontal, vertical, or infill, depending on the building's configuration. Feasibility of expansion based on size of property, existing coverage, regulatory restrictions, and physical constraints such as topography and proximity to natural resources.

### ***Feasibility of Site Expansion***

Evaluation of whether site expansion is possible, based on adjacent properties, and physical constraints, such as roads, proximity to protected lands, and easements.

## **Community Assessment: Site Evaluation**

The Community – Site assessment included the broad categories of transportation access and neighborhood elements. Transportation access considered the condition of the adjacent streets, the ability of students and adults to bicycle and walk to the school, and the accessibility of public transportation. Neighborhood elements considered the school's proximity to community, civic, educational, commercial, and athletic facilities.

### ***New Hampshire Division of Historical Resources (DHR) Status Inventory of Archeological Assets (Site Review)***

Comment, if applicable. Criteria will inform opportunities and constraints for modifying the existing building. In some cases, data may not be available.

### ***School Buses***

Review of types and numbers of school buses and bus queuing.

### ***Accessible to Transit***

Building is located within 2 blocks (1000 feet) of at least 2 stops on bus lines of regular frequency (at least every 10 minutes, during rush hour and mid-afternoon). Criteria noted and considered as part of the overall community building score.

### ***Bikeable***

Facility is considered bikeable if within 2 miles of multiple residential neighborhoods, without riding on busy streets that lack dedicated bike areas. Criteria noted and considered as part of the overall community building score.

- » Wide sidewalks and/or low-traffic streets
- » Adjacent to or within a residential neighborhood, without crossing busy & wide (4+ lanes) streets
- » Not located on a steep street
- » Bike racks are present at the school and are safely accessed from site entry points

**Walkable**

Facility is considered walkable if within 1.4 miles of residential neighborhoods, with consistent sidewalks, and walking route does not require students to cross busy or dangerous streets (per district eligibility criteria).

- » Consistent, accessible sidewalks with crosswalks
- » Adjacent to or within a residential neighborhood, without crossing wide (4+ lanes) streets

**Site suitability for school use?**

Yes/No, Comment if applicable. Considers overall site conditions, overall community rating, and size of site.

**Overall Building – Community Condition:**

This is the professional judgment on the part of the reviewer(s), considering all aforementioned factors and with consideration of nearby neighborhood, community, educational, and athletic facilities. Criteria noted and considered as part of the overall community building score.

# Educational Assessment Criteria

## Educational Facility Effectiveness Evaluation

### Educational Facility Effectiveness of Learning Environments (EFE-LE)

The quality of physical environments has direct impacts on educational outcomes. The EFE analysis considers both inherent building characteristics of physical appearance and condition, and introduced equipment (e.g., furniture and technology). These qualitative factors have a large impact on overall student performance, as they influence students' comfort and ability to concentrate on tasks; teacher and student health and wellness; as well as absenteeism and retention.

Building environments also affect the overall educational effectiveness rating. Fixed elements, such as walls and windows, are components that are not easily remedied and may require extensive or invasive renovation. Other elements, such as furniture or finishes, can be more easily updated, replaced, or supplemented.

Fixed Building Elements include:

- » Ventilation
- » Natural Daylighting
- » Lighting Quality
- » Acoustical
- » Environment (Inviting/Stimulating/Comfortable)
- » Power and Technology Infrastructure
- » Access to water for student projects
- » Access to toilet facilities

Repairing these fixed elements may require buildings to be unencumbered of students (i.e., vacant) for the duration of the work, depending on the upgrades required.

- » Adaptable elements
- » Technology: ubiquitous wireless access for teachers and students and classroom technology
- » Furniture: light weight, ergonomic and supportive of collaboration
- » Finishes
- » Adjacencies of Learning Environments
- » Access to outdoor learning (classrooms or other)

These considerations often consist of singular systems and can be repaired or replaced independent of other systems. They may change frequently with the evolving landscape of educational pedagogy and should support a building that can adapt flexibly at relatively low costs. These upgrades can be executed internally, by facilities personnel or with arranged contracts.

## Educational Facility Effectiveness Evaluation: Criteria Rating Hierarchy

The EFE-LE uses the following classification system:

- Excellent: Elements meet needs for 21st century (Next Generation) teaching and learning
- Good: Elements contribute to teaching and learning
- Fair: Elements somewhat interfere with teaching and learning
- Poor: Elements detract from or interfere with teaching and learning
- Deficient: Non-existent or inoperable systems or elements

## Educational Facility Effectiveness Evaluation: Analysis Definitions

### ***Evaluation Criteria***

**Building Originally Designed As:** Over time, a school building may have modified the range of grades served. Knowing their original use quickly provides some insight into space types and building appointments.

### ***Best Grade Configuration for this School Building***

A school building may be best suited for a different range of grades or use depending on the types, quantities, and sizes of spaces, as well as the existing site attributes, including:

- » Heights of casework, markerboards and other elements the students use
- » Configuration and heights of toilet room fixtures

### ***Ventilation***

Fresh air is a critical component for health, wellness, and overall student performance. An even distribution of ventilated air is also important. Different ventilation systems (unit ventilators, central air ventilation, no mechanical ventilation) provide varying levels of outdoor air percentages and filtration. Observe whether mechanical ventilation is provided and what the apparent quality of the ventilation system is. Qualitative measurements are not taken, however visual, olfactory, and thermal observations are made.

### ***Natural Daylighting***

Considered to be a better quality of light than artificial lighting. Evaluates the general quantity/quality of the natural light and note if most spaces have access to daylight.

### ***Artificial Lighting Quality***

Observed (not measured) light level at the working surface. Type of light fixture and whether it provides an even dispersion of light for general academic tasks, and whether the fixture is dimmable, to accommodate use of technology.

**Acoustical**

The proper balance between voice reinforcement and sound absorption impacts “speech intelligibility.” This includes both sound performance within the space, as well as sound coming from outside the space. Observe whether the space appears to have appropriate acoustical properties for teaching and learning.

**Technology (Power):**

There are enough electrical outlets to support a future technology-rich classroom/school and they are properly distributed throughout the space.

**Technology (Wireless):**

There are sufficient access points throughout the school to support a 1:1 technology environment and fiber optic wiring exists within the building. The main distribution room (server room) is air-conditioned, to ensure system reliability.

**Technology (Interactive):**

Classrooms and other teaching spaces have working interactive technology, such as interactive marker boards and document cameras.

**Furniture**

Different educational-delivery models can be reinforced by furniture type and flexibility. Ideal furniture is light and mobile enough to be easily re-arranged in multiple configurations. Furniture is ergonomic, comfortable, in good condition and promotes student collaboration.

**Finishes**

Materials and conditions of the walls, floors and ceilings. Both physical and aesthetic conditions are considered.

**Environment (Inviting/Stimulating/Comfortable)**

Evaluates whether building is aesthetically pleasing and if it is a place where students and teachers feel comfortable and want to spend time in each day.

**Adjacencies of Learning Environments**

Classrooms and other learning environments have a relationship to each other which promotes collaboration, communication, and other aspects of 21st century teaching and learning. Spaces promote interdisciplinary learning.

**Outdoor Classrooms**

Students have access to outdoor classrooms or other outdoor learning opportunities to learn in different ways, sometimes involving nature and hands-on activities.

## **Site Components**

### ***Playgrounds/Play Areas***

Description of play surface materials (hard or soft). Evaluates condition of on-site play structures and whether structures are age-appropriate to the school's student population.

### ***Accessibility***

Evaluates conditions of play areas, including the ground surface/material, and whether areas are accessible to children of various disabilities.

### ***Play Fields***

Describes conditions of play fields, if present, and whether fields natural grass or synthetic turf.

### ***Flexibility in Building Typology***

Evaluates whether the building can serve alternative grade levels or support a special needs-focused curriculum.

### ***Educational Transformation to Support 21st Century Needs***

Evaluates if the building's construction easily allows for renovations that may change room sizes, replace or upgrade mechanical and electrical systems, and accommodate alternative educational-delivery methods (e.g., project-based learning [PBL]). This can often be the largest difference between a modern steel-frame building and interior masonry-bearing wall construction.

### ***Building as Swing Space***

Assuming the building is otherwise unoccupied, the ability to use the building for educational purposes for the temporary relocation of a school population during a period of renovation or construction.

### ***Utilization Rate***

Description of the utilization rate and if it is 85% or higher. For high schools, classroom utilization of 85% are considered at capacity. Rates higher than 85% show levels of overcapacity and overcrowding. Middle schools generally work to a utilization of 90% and elementary schools at near 100%.

# Educational Facility Spaces Effectiveness Evaluation

The Educational Facility Effectiveness – Spaces (EFE-S) metric compares the sizes of educational spaces to the New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines for 21st century teaching and learning in new capital projects. This quantitative analysis is important for establishing the level of adequacy of the existing spaces for educational delivery. It also indicates whether a facility is deficient/missing dedicated educational spaces normally found in buildings of its grade level and typology.

Primary considerations often affect core curriculum and include:

- » Classrooms (Depending on typology, these may include Pre-K and Kindergarten)
- » Teacher Planning
- » Small Group
- » Science
- » Art
- » Music
- » Vocations and Technology
- » Media Center
- » Cafeteria

Secondary considerations may allow for district flexibility in programming and community resources outside the traditional building environment, and include:

- » Gymnasium (This program space is sometimes served by local community spaces)
- » Gymnasium Options
- » Auditorium
- » Stage
- » Medical
- » Administration & Guidance
- » Air Conditioned Technology Network Room
- » Other considerations
- » Special Education: Self-Contained
- » Special Education: Resource or Small Group

Note: If a school has a special education program, its quantity of spaces will vary. Also, some substantially separate programs do not require full-size classrooms to be effective. For this reason, special education was considered differently than typical classroom spaces.

## Educational Facility Spaces Effectiveness Evaluation: Criteria Rating Hierarchy

The educational facility effectiveness assessment for spaces used a quintile classification hierarchy as defined below:

- Excellent: Exceeds New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines (+10% or greater)
- Good: School facilities are appropriate to house current enrollment and educational program. NSF meets New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines (-10% to +10%)
- Fair: School facilities appear to be adequately sized for current enrollment and educational program. NSF somewhat less than New Hampshire Code of Administrative Rules, Section Ed. 321 (-10% to -20%)
- Poor: School facilities may not be adequately sized for current enrollment and educational program. Net square footage (NSF) at least 20% less than New Hampshire Code of Administrative Rules, Section Ed. 321 guidelines
- Deficient: Dedicated space does not exist.

## Educational Facility Spaces Effectiveness Evaluation: Analysis Definitions

### ***Narratives***

The team considered the long-term goals relative to each building's capability of supporting Manchester School District's educational vision for 21st century (next generation) learning and teaching.

### ***Engaged Learning***

Engaging with the curriculum, applying it to an authentic context. Making connections between content areas and values/curiosity and interest. Finding connections to the community and making a difference. Public and tangible products. There is selective and intentional engagement, and agency in how one keeps focused and takes breaks.

- » The following were criteria used for evaluating the levels of Engaged Learning at each school:
- » The building (is/is not) comfortable to learn in.
- » The building (has/lacks) appropriate temperature control and ventilation.
- » The building (has/lacks) a space that can be used as a flexible learning commons for collaborative learning and presentations.
- » The building (makes use/does not make use) of public space for teaching and learning.
- » The building (provides/lacks) display space for student work to reinforce student accomplishments.
- » The building (provides/lacks) space for teacher collaboration and planning.

### ***Differentiated Learning***

Acknowledging different learning styles. Encouraging how to understand one's self (self-knowledge). Flexibility that occurs within instruction, which also promotes flexibility in how students demonstrate learning. The following were criteria used for evaluating the levels of Differentiated Learning at each school:

- » Classrooms (are/are not) large enough to support Universal Design for Learning (UDL), including the ability to create learning zones.
- » The building (has/lacks) breakout spaces for differentiated/personalized learning and special education.
- » The furniture in the building (can be/has difficulty being) flexibly arranged.

### ***Cognitively Demanding Tasks/Programs***

- » The classroom environment (is/is not) sufficiently flexible to allow for different teaching and learning styles.
- » Building (supports/lacks) learning environments that support music.
- » Building (supports/lacks) learning environments that support art.
- » Building (supports/lacks) learning environments that support physical activity/education.
- » The building environment (supports/does not support) STEM adequately.
- » The building (provides/lacks) space to experiment, create and collaborate.
- » The building (has/lacks) performance/presentation space.
- » Based on location and proximity to community resources and public transportation, teachers and students (can/have difficulty) access(ing) the City as a learning tool.

## **Overall EFE Rating**

NH Code of Administrative Rules, Section Ed. 321 areas are based on current enrollment within school. Actual areas were determined by measuring CADD plans provided by Manchester School District. SMMA did not field-measure the buildings but verified general conformity with existing conditions by measuring spot values to determine the rough accuracy of CADD drawings. The design team reviewed the 2018 CMK Long-Range Facilities Plan, which informed some of the educational effectiveness ratings.

The following outlines the rating system used for evaluating the Overall Educational Facility Effectiveness:

- Excellent: Elements meet needs for current AND future teaching and learning.
- Good: Elements contribute to teaching and learning.
- Fair: Elements somewhat interfere with teaching and learning.
- Poor: Elements detract from or interfere with teaching and learning.
- Deficient: Non-existent or inoperable systems or elements.

